

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20005645/BBA3Q2

Date: 26/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700070991

Claimant
Vehicle No : YQ290T **Insured Vehicle No :** GBD3266K

Date of Loss: 08/05/2020 Nature of Claim: TP Claim No: 1587215759SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YQ290T		
Make & Model:	ISUZU NQR75UL5A, 5.2 D (M)	Engine No:	4HK1760108
Reg. Date:	13/02/2019 (Man. Year: 2018)	Chassis No:	JAAN1R75LJ7101904
Colour:	White	Odometer:	0 km
Engine Capacity:	5193 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 17.5	Rear Tyre Size:	215/75 17.5
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,391.62	8,002.84	12,388.78	60.75
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	4,560.00	1,440.00	24.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	26,391.62	12,562.84	13,828.78	52.40
Approved Total (Overridden) (\$\$)		10,050.00		
Nett Amount (\$\$)	26,391.62	10,050.00	16,341.62	61.92
+ Car Rental (11.0 x S\$180.00/day) (\$\$)		1,980.00		
+ Doc/Search Fee (\$\$)		7.45		
+ Other Costs (\$\$)		130.00		
Nett Liability (\$\$)		12,167.45		
Global Sum Settlement (\$\$)		12,100.00		

INSPECTION

Date of Assignment: 11/05/2020

Date Inspected: 11/05/2020 Inspected At:

Team Auto Pro Pte Ltd - Sin Ming
(HQ)
160 Sin Ming Drive #01-14 Sin Ming
Autocity
Singapore 575722

Estimated Period of Repair: 14.0 days

Adjuster: Lim Teow Guan**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SLIDING DOOR (FRONT)	Dislodged	4,800.00 FL	*2,000.00 FL
2	1		*SLIDING DOOR (REAR)	Bent	4,800.00 FL	*2,000.00 FL
3	2		*SLIDING RALLS UPPER	Not Damaged	1,500.00 FL	*- FL
4	2		*SLIDING RALLS LOWER	Bent	1,484.60 FL	*400.00 FL
5	2		*SLIDING DOOR ROLLER UPPER	Necessary	516.60 FL	*200.00 FL
6	2		*SLIDING DOOR ROLLER LOWER	Necessary	513.60 FL	*200.00 FL
7	2		*SLIDING DOOR LOCK	Bent	370.64 FL	*370.64 FL
8	1		*DOOR FRAME	Bent	1,200.00 FL	*1,200.00 FL
9	2		*DOOR HANDLE	Not Damaged	172.00 FL	*- FL
10	2		*CHECKER	Necessary	268.00 FL	*268.00 FL
11	1		*ALUMINIUM PLATE	Torn	1,600.00 FL	*1,600.00 FL
12	1		*SAFETY BAR	Not Damaged	950.00 FS	*- FS
13	2		*STEP BAR	Repair	1,200.00 FS	*- FS
14	1		*FLOOR BOARD	Not Damaged	1,600.00 FS	*- FS
15	1		*STICKER	Necessary	2,000.00 FS	*1,000.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	22,975.44	9,238.64
- List Item Discount on L Items 15.00/15.00% (\$)	2,583.82	1,235.80
Total Parts (\$)	20,391.62	8,002.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R SAFETY BAR	New	150.00	0.00
2	R&R FLOOR BOARD	New	300.00	0.00
3	R&R STEP BAR	New	150.00	80.00
4	PANEL BEATING	New	2,800.00	2,400.00
5	SPRAY PAINTING	New	2,400.00	2,000.00
6	RUST PROOFING	New	200.00	80.00
Gross Labour Cost (S\$)			6,000.00	4,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >