

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: FWD Singapore Pte Ltd
Date: 11/05/2020
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLQ4906D
 CHASSIS NO : NHP1707063305
 MAKE / MODEL : Toyota Sienta Hybrid 1.5X Auto
 DATE OF ACCIDENT : 28/04/2020
 YOUR INSURED VEHICLE NUMBER : SJT6509Y
 MILEAGE : 151542 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
	1 Rear tailgate / PD	1PC	\$ 1,879.00	\$ 1,879.00
	2 Rear tailgate weatherstrip / CRU.	1PC	\$ 432.00	\$ 432.00
	3 Rear tailgate lock / Jan	1PC	\$ 504.00	\$ 504.00
	4 Rear tailgate lock catch xsvc.	1PC	\$ 64.80	\$ 64.80
	5 R/R tail lamp / Mrs	1PC	\$ 550.00	\$ 550.00
	6 R/R taillamp reflector ? xsvc	1PC	\$ 380.00	\$ 380.00
	7 R/L taillamp reflector ? / CRA	1PC	\$ 380.00	\$ 380.00
	8 Rear tailgate center garnish ? xsvc	1PC	\$ 342.00	\$ 342.00
	9 Rear tailgate HYBRID logo / Nec	1PC	\$ 60.00	\$ 60.00
photo	10 Rear end panel / PD	1PC	\$ 828.00	\$ 828.00
photo	11 Rear end panel lower / PD	1PC	\$ 633.60	\$ 633.60
	12 Rear end panel top garnish / CRM	1PC	\$ 250.00	\$ 250.00
	13 Rear bumper reinforcement x NN	1PC	\$ 338.10	\$ 338.10
	14 Rear bumper sponge x NN	1PC	\$ 157.50	\$ 157.50
	15 Rear bumper cover / SCR	1PC	\$ 1,257.83	\$ 1,257.83
	16 Rear bumper RH retainer ? xsvc	1PC	\$ 67.05	\$ 67.05
	17 Rear bumper LH extension pad x R	1PC	\$ 216.00	\$ 216.00
	18 Rear bumper RH extension pad ? / Def	1PC	\$ 216.00	\$ 216.00
	19 Rear bumper center pad / CRM.	1PC	\$ 288.00	\$ 288.00
	20 Rear bumper LH reflector ? xsvc	1PC	\$ 93.60	\$ 93.60
	LIST TOTAL S\$:		\$	8,937.48
	25.00% DISCOUNT S\$:		\$	2,234.37
			\$	6,703.11

SPECIAL NETT

1	Bumper clips / Nec	1 SET	\$ 80.00	30
2	Reverse sensor / NIC	1 SET	\$ 260.00	200
3	Windscreen sealant / Nec	1PC	\$ 100.00	40
4	Body sealant / Nec.	1PC	\$ 300.00	40
	Special Nett Total S\$:		\$	740.00

LABOUR CHARGES

- | | | |
|---|---|-----------------|
| 1 | To remove and install rear tailgate glass | \$ 120.00 ✓ |
| 2 | Transfer tailgate mechanism | \$ 100.00 60 |
| | To labour charge for removing rear tailgate, rear bumper, end | |
| 3 | panel and spare tyre panel out to facilitate repairs and | \$ 1,000.00 800 |
| | replacemnt of damaged parts | |
| 4 | To respray rear tailgate, rear end panel, | \$ 1,000.00 800 |
| | spare tyre panel and rear bumper | |

LABOUR TOTAL S\$:	\$ 2,220.00
TOTAL S\$:	\$ 9,663.11
7% GST	\$ 676.42
GRAND TOTAL S\$:	\$ 10,339.53

Sun Pm (LKK)
12/05/2010
TP without prejudice.

Repair day - 5 days
L/S
After paint photo.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: FWD Singapore Pte Ltd
Date: 18/06/2020
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLQ4906D
CHASSIS NO : NHP1707063305
MAKE / MODEL : Toyota Sienta Hybrid 1.5X Auto
DATE OF ACCIDENT : 28/04/2020
YOUR INSURED VEHICLE NUMBER : SJT6509Y
MILEAGE : 151542 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	R/L taillamp / CRU.	1PC	\$ 550.00	\$ 550.00
2	R/R taillamp LED combination socket / cut	1PC	\$ 280.00	\$ 280.00
3	R/R taillamp LED wiring X SVC.	1PC	\$ 200.00	\$ 200.00
4	Rear tailgate holder hand grip / Def.	1PC	\$ 180.00	\$ 180.00
5	Rear tailgate tray box / CRU	1PC	\$ 580.00	\$ 580.00
6	Rear antenna sensor / CRA	1PC	\$ 120.00	\$ 120.00
			LIST TOTAL S\$:	\$ 1,910.00
			25.00% DISCOUNT S\$:	\$ 477.50
				\$ 1,432.50
			7% GST	\$ 100.28
			GRAND TOTAL S\$:	\$ 1,532.78