



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007655
INV Date 13/11/2020
Reference CC4/FCI20005652/Kea3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLV 1533P
Insured Veh. SHA 1689G
Claim No. D20002076MFSH
Policy No. D-20094922MFSH
Accident Date 25/04/2020
Inspection Date 18/05/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20005652/Kea3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 13-11-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1689G	Veh. Inspected	SLV 1533P	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20002076MFSH	Excess (\$)	0.00	
Assign From	VIC	Assign Date	11/05/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	ZYX102075097	Colour	METALLIC PEARL WHITE	
Odometer	69932	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/50 R18	BRIDGESTONE	7 mm	
L/H Front Tyre	225/50 R18	BRIDGESTONE	7 mm	
R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2020	Inspection Date	18/05/2020	
Survey held at	OPTIMA WERKZ PTE LTD 9A SERANGOON NORTH AVE 5 SINGAPORE 554500			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLV 1533P

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
8	FRONT BUMPER CLIPS @\$5.80	NECESSARY	46.40	46.40
8	FRONT FENDER INNER LINER CLIPS LH @\$5.50	NOT NECESSARY	44.00	-
1	FRONT BUMPER SIDE BRACKET LH	SERVICEABLE	105.30	-
1	FRONT FENDER EXTENSION COVER LH	DENTED / CUT	148.60	148.60
1	FRONT BUMPER (NPA)	TO REPAIR SEE LABOUR	-	-
1	FRONT FENDER LH (NPA)	TO REPAIR SEE LABOUR	-	-
	LESS 25% DISCOUNT		-86.08	-48.75
			258.22	146.25
	<u>LABOUR</u>			
	LABOUR CHARGES TO REMOVE, REPAIR ,REPLACE ,REFIX & READJUST FRONT ACCIDENT AREAS & ETC.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH AND FRONT BUMPER .		400.00	300.00
	LABOUR CHARGES TO REMOVE & REFIX FRONT BUMPER PARKING SENSOR & ETC .TO EFFECT REPAIR AT FRONT BUMPER .		80.00	50.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNNING MATERIALS AT FRONT BUMPER ,FRONT FENDER LH & ETC (PEARL WHITE).		600.00	440.00
			1,080.00	790.00
	GRAND TOTAL		1,338.22	936.25
	RECOMMENDED COST OF REPAIRS			936.25

Report Ref No. CC4/FCI20005652/Kea3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLV 1533P

INSPECTION






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

