

Date: 04.05.2020
 Vehicle No: SLV1533P
 Model: TOYOTA CHR HYBRID 1.8G
 Chassis: ZYX102075097-2017
 Reg.Year: 2017

Third Party Insurer: MS FIRST
 Third Party Veh No: SHA1689G
 Date of Accident: 25.04.2020

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	8	\$5.80	\$46.40
2	FRONT FENDER INNER LINER CLIPS LH	8	\$5.50	\$44.00
3	FRONTBUMPER SIDE BRACKET LH	1		\$105.30
4	FRONT FENDER EXTENTION COVER LH	1		\$148.60
5	FRONT BUMPER	1		REPAIR
6	FRONT FENDER LH	1		REPAIR
SUB TOTAL				\$344.30
LESS 25%				-\$86.08
PARTS TOTAL				\$258.23

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPAIR, REPLACE, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.

\$400.00 300

LABOUR CHARGES TO REMOVE & REFIX FRONT BUMPER PARKING SENSOR & ETC. TO EFFECT REPAIR AT FRONT BUMPER.

\$80.00 50

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT FENDER LH & ETC. (PEARL WHITE)

\$600.00 440

LABOUR TOTAL \$1,080.00

TingAn

TOTAL \$1,338.23

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

