

EFFICIENT MOTOR & ENGINEERING WORKS PTE LTD

56 LOYANG WAY # 06-07 ENTERPRISE BUILDING SINGAPORE 508775

VEHICLE NO : GBH207E

MAKE & MODEL : NISSAN CABSTAR

CHASSIS NO : JN1SC2F24Z0860739

DATE : 11 MAY 2020

CLAIM TYPE : OD CLAIM

D.O.A : 08 MAY 2020

TO : INDIA INTERNATIONAL INSURANCE PTE LTD

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	COST PRICE	TOTAL PRICE
1	1	FRONT WINDSCREEN GLASS / <i>RR</i>		\$ 580.00	\$ 580.00
2	1	FRONT WINDSCREEN GLASS MOULDING / <i>IPC</i>		\$ 270.00	\$ 270.00
3	1	RH FRONT CORNER PANEL TOP / <i>MIS</i>		\$ 75.00	\$ 75.00
4	1	RH FRONT CORNER PANEL SIDE / <i>OD</i>		\$ 75.00	\$ 75.00
5	1	HEADLAMP RH / <i>CHT</i>		\$ 230.00	\$ 230.00
6	1	HEADLAMP LOWER PANEL RH / <i>CHT</i>		\$ 50.00	\$ 50.00
7	1	LH FRONT CORNER PANEL TOP / <i>OD</i>		\$ 18.00	\$ 18.00
8	1	FRONT GRILLE / <i>CRH</i>		\$ 260.00	\$ 260.00
9	1	FRONT GRILLE LOWER GARNISH X <i>NN</i>		TBC	\$ -
10	1	FRONT BUMPER / <i>RR</i>		\$ 490.00	\$ 490.00
11	1	RH FRONT DOOR / <i>OD</i>		\$ 780.00	\$ 780.00
12	1	RH FRONT DOOR SIGNAL LAMP X <i>NN</i>		\$ 20.00	\$ 20.00
13	2	RH FRONT DOOR HINGE / <i>OD</i>		\$ 30.00	\$ 60.00
14	1	RH FRONT DOOR RUBBER X <i>NN</i>		\$ 80.00	\$ 80.00
15	1	RH FRONT DOOR STEP GARNISH / <i>RR</i>		\$ 100.00	\$ 100.00
16	1	WASHER TANK / <i>X NN</i>		\$ 85.00	\$ 85.00
17	1	LH FRONT DOOR / <i>OD</i>		\$ 780.00	\$ 780.00
18	1	LH FRONT DOOR SIGNAL LAMP / <i>CHT</i>		\$ 20.00	\$ 20.00
19	1	LH FRONT TYRE INNER SHIELD (REAR) / <i>CHT</i>		\$ 155.00	\$ 155.00
20	1	DIESEL FUEL TANK / <i>OD</i>		\$ 800.00	\$ 800.00
21	2	DIESEL FUEL TANK BRACKET / <i>BT</i>		\$ 100.00	\$ 200.00
22	2	DIESEL FUEL TANK BRACKET RUBBER / <i>IPC</i>		\$ 50.00	\$ 100.00
23	1	LH SIDE GATE / <i>OD</i>		\$ 2,080.00	\$ 2,080.00
24	2	LH SIDE GATE RUBBER STOPPER / <i>MIS/CHT</i>		\$ 10.00	\$ 20.00
25	1	LH WING MIRROR (BIG) / <i>CHT</i>		\$ 115.00	\$ 115.00
26	1	AIR CLEANER FILTER / <i>RR</i>		\$ 90.00	\$ 90.00
				\$ 7,343.00	\$ 7,533.00

TOTAL PRICE \$ **7,533.00**
 PLUS 10% \$ **753.30**
 SUB TOTAL PRICE \$ **8,286.30**

7348
+10%
8082.80

S/No.	QTY	DESCRIPTION	CONDITION / REMARKS	UNIT S/NETT	TOTAL S/NETT
29	1	SEALANT / <i>IPC</i>		\$ 40.00	\$ 40.00
30	1	INNER SEAL / <i>IPC</i>		\$ 20.00	\$ 20.00
31	1	ERP BRACKET / <i>IPC</i>		\$ 26.00	\$ 26.00
32	1	FRONT NUMBER PLATE / <i>III</i>		\$ 35.00	\$ 35.00
33	1	RH FRONT DOOR STICKER CO.REG. ADDRESS / <i>RR</i>		\$ 15.00	\$ 15.00
34	1	LH FRONT DOOR STICKER CO.REG. ADDRESS / <i>RR</i>		\$ 15.00	\$ 15.00
35	1	LH SIDE GATE CHECKER PLATE / <i>CHT (MAY 16)</i>		\$ 650.00	\$ 650.00
36	1	ENGINE OIL (5L) / <i>RR</i>		\$ 120.00	\$ 120.00

TOTAL S/NETT

\$ **921.00** \$ **921.00**

Labour Charges

31	TO REMOVE & INSTALL FRONT WINDSCREEN GLASS.			\$ 120.00	/
32	TO KNOCK, STRAIGHTEN & RENEW ACCIDENT AREA SUCH AS FRT BUMPER, FRT PANEL			\$ 1,600.00	1200
	RH FRT CORNER PANEL TOP, RH FRT CORNER PANEL SIDE, HEADLAMP RH, RH FRT DOOR,				

875

	LH FRT DOOR, LH FRT WINDSCREEN PILLAR, FRT CABIN REAR PANEL RH, FRT FLOOR PANEL, LH SIDE GATE AND ETC.		
33	TO PUTTY & RESPRAY ACCIDENT AREA SUCH AS FRT PANEL, FRT GRILLE LOWER	\$ 2,000.00	1200
	GARNISH, RH FRT CORNER PANEL TOP, RH FRT CORNER PANEL SIDE, RH FRT DOOR, LH FRT DOOR, LH FRT WINDSCREEN PILLAR, CABIN REAR PANEL, RH FRT FLOOR PANEL, LH SIDE GATE PANEL, LH FRT CORNER SIDE PANEL AND ETC		
34	TO REMOVE & TRANSFER RH FRT DOOR COMPONENTS TO NEW DOOR.	\$ 100.00	80
35	TO REMOVE & TRANSFER LH FRT DOOR COMPONENTS TO NEW DOOR.	\$ 100.00	80
36	TO REMOVE AND INSTALL DIESEL FUEL TANK.	\$ 200.00	100
37	TO REMOVE & INSTALL LH SIDE GATE CHECKER PLATE.	\$ 200.00	150
38	TO CHECK WIRING AND LIGHTING.	\$ 50.00	30
39	TO CONDUCT WHEEL ALIGNMENT.	\$ 80.00	60

TOTAL LABOUR

\$ 4,450.00

Total Cost of Repairs

\$ 13,657.30

(Total parts + Total S/Nett + Total Labour Cost)

Steve (LKK)
8322 8813

OD - Not Authorise

Excess - ?

12/5/99, 10.00 am

12 days

L/S

My After day

P-8082-80

N-875

L-3020

11,977-80

L/S-9582-24

= 9600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: