

ESTIMATE

HOE HUI SHAN

c/o 46 Lentor Plain
Singapore 786548

Not Notified
1/1 Imp & 1/4 Sub 1700h
Resurvey After Paint
4 days

Date: 12/5/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA ALTIS / SJV 9983 U		
1 pc	front bumper 465	494.40
1 pc	front bumper side retainer	60.66
1 pc	front bumper fog lamp 301.50	349.80
1 pc	front bumper fog lamp garnish 120.60	180.25
1 pc	front bumper reinforcement	371.20
1 pc	front bumper sponge	284.25
1 pc	front head lamp assy	462.40
1 pc	front fender	348.50
sub-total		2,551.46
less 25%		637.87
sub-total		1,913.60
To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		600.00
To check wiring system.		40.00
To apply putty and spray painting on affected areas.		580.00
Total		3,133.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: