

ASS. REC. BY:

REF:

AIG/20003657/kk

C

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP / 24 HRS

5/29

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STQ 51464

Yr Regn:

05, 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MIT Lancer EX c.c.

1998

Colour

M. Red

A/C:

Insured / Std / NI / NA

Sp. Reading

37318P

T/Radio:

Insured / Std / NI / NA

Eng/No:

7

C/No:

JMYSTCY4A 9.4 001614

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

14/4/20

D.O.I.

11/5/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S R

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

15/6 11am @ 3350h email & confirmed

Date/Time, File Pass to?

☐

: Prel. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Report Format :

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS: \$

Fixtures

Others

TOTAL

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

Not Notified
61 Sup @ 3350/2
Returning After Paint
4 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: _____ Third Party

Date: 06.05.2020

Accident Date : 14.04.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mitsubishi Lancer 2.0" Reg. No. SJQ5146Y Claiming Against Your Insured Reg. No. SCX8855K			
1pc	Front Bumper 801	4.00	Bu 896.00 ✓
14pc	Front Bumper Clips		ru 56.00 ✓
1pc	Front Bumper Top Rubber Seal		ru 29.00 ✓
1pc	Front Bumper Top Beam		R 75.00 X
1pc	Front Bumper Fog Lamp RH 430		CMs 458.00 ✓
1pc	Front Bumper Fog Lamp Cover RH		wa 39.00 ✓
1pc	Front Bumper Corner Retainer RH	9.00	D.I 14.20 ✓
12pcs	Front Bumper Rivets		ru 108.00 ✓
1pc	Front Bumper Reinforcement		R 356.00 X
1pc	Front Headlamp RH 1036		MJ car 1,132.00 ✓
1pc	Front Bumper Lower Panel RH		R 182.00 X
1pc	Front Fender RH 496		R 535.00 ✓
1pc	Front Fender Inner Shield RH	4.00	ms 115.00 ✓
10pcs	Front Fender Inner Shield Clips		ru 40.00 ✓
1pc	Wiper Tank		Dol 82.00 ✓
1pc	Wiper Tank Motor		ru 82.00 X
1pc	Front Shock Absorber RH		ru 469.00 X
1pc	Front Knuckle Arm RH		ru 326.00 X
1pc	Front Knuckle Arm Bearing RH		ru 150.00 X
1pc	Front Wheel Hub RH		ru 235.00 X
1pc	Front Lower Arm RH		ru 321.00 X
	Less 10%		5,700.20
			570.02
			5,130.18
1pc	Front Sport Rim RH		ru 480.00 SN
1pc	Front Tyre RH		ru 280.00 SN X
		C/F	5,890.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 06.05.2020

Accident Date : 14.04.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mitsubishi Lancer 2.0" Reg. No. SJQ5146Y Claiming Against Your Insured Reg. No. SCX8855K		
		B/F	5,890.18
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		40.00 20/
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		80.00 30/
	To Dismantle / Replace Front Under Carriage	nn	200.00 X
	To Conduct Computerize Wheel Alignment Test		80.00 60/
	To Conduct High Speed Balancing		80.00 20/
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel, Door Pillar, and Parts Replacement		800.00 400/
	To Respray Affected Areas		700.00 440/
		Total :	<u>7,870.18</u>