

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

Not Authorised
L1 Surp @ ?
Resurvey After Paint
4 days

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: _____ Third Party

Date: 06.05.2020

Accident Date : 14.04.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Mitsubishi Lancer 2.0" Reg. No. SJQ5146Y Claiming Against Your Insured Reg. No. SCX8855K			
1pc	Front Bumper	4.00	Bu 896.00 ✓
14pc	Front Bumper Clips		Mu 56.00 ✓
1pc	Front Bumper Top Rubber Seal		Mu 29.00 ✓
1pc	Front Bumper Top Beam		R 75.00 X
1pc	Front Bumper Fog Lamp RH		CM 458.00 ✓
1pc	Front Bumper Fog Lamp Cover RH		W 39.00 ✓
1pc	Front Bumper Corner Retainer RH		D 14.20 ✓
12pcs	Front Bumper Rivets	9.00	M 108.00 ✓
1pc	Front Bumper Reinforcement		R 356.00 X
1pc	Front Headlamp RH		M 1,132.00 ✓
1pc	Front Bumper Lower Panel RH		R 182.00 X
1pc	Front Fender RH		B 535.00 ✓
1pc	Front Fender Inner Shield RH		M 115.00 ✓
1pc	Front Fender Inner Shield Clips	4.00	M 40.00 ✓
10pcs	Wiper Tank		82.00 ?
1pc	Wiper Tank Motor		B 82.00 X
1pc	Front Shock Absorber RH		B 469.00 X
1pc	Front Knuckle Arm RH		326.00 X
1pc	Front Knuckle Arm Bearing RH		150.00 X
1pc	Front Wheel Hub RH		235.00 X
1pc	Front Lower Arm RH		321.00 X
			5,700.20
			570.02
	Less 10%		5,130.18
1pc	Front Sport Rim RH		Net 480.00 SN
1pc	Front Tyre RH		M 280.00 SN X
		CIF	5,890.18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: AIG Asia Pacific Insurance Pte Ltd

Policy No: Third Party

Date: 06.05.2020

Accident Date : 14.04.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost Of Repair To "Mitsubishi Lancer 2.0" Reg. No. SJQ5146Y Claiming Against Your Insured Reg. No. SCX8855K		
		B/F	5,890.18
	To Conduct Front Electrical Check, Locking System, Adjust, Focus Headlamp etc		40.00 201
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		80.00 301
	To Dismantle / Replace Front Under Carriage		nn 200.00 X
	To Conduct Computerize Wheel Alignment Test		80.00 601
	To Conduct High Speed Balancing		80.00 201
	Labour Charge - Panel Beating, Repairing Of Front Fender Inner Panel, Door Pillar, and Parts Replacement		800.00 4001
	To Respray Affected Areas		700.00 6401
		Total :	<u>7,870.18</u>