

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Jm6KF2W7AJ01S5771

SABIR AHMED S/O N A ABDUL WAHAB
BLK 101C PUNGGOL FIELD
#03-462
S 823101

TPAXA
Jasper

Date :13.05.2020
Vehicle No :SLW 9710 L
Make/Model :MAZDA 5
Accident date :08.05.2020

No	DESCRIPTION	Qty	Amount (\$\$)
List Items			
1	Rear bumper Distorted	1	\$ 1405.80
2	Rear bumper towing hook cover Missing	1	\$ 70.00
3	Rear bumper side holder @ \$26.10 New	2	\$ 52.20
4	Rear bumper top rubber Deformed	1	\$ 95.00
5	Rear bumper RH reflector New	1	\$ 231.00
6	Rear bumper reinforcement Deformed	1	\$ 675.40
7	Rear bumper bracket @ \$39.60 Best	2	\$ 79.20
8	Rear bumper clips (1 set) New	1	\$ 70.00
9	Rear end panel New	1	\$ 645.70
10	Rear end panel top garnish New	1	\$ 462.00
11	Rear tailgate Repair	1	\$ 1886.50
12	Rear tailgate centre logo	1	\$ 50.80
13	Rear tailgate CX 5 emblem } New	1	\$ 94.00
14	Rear tailgate SkyActiv emblem	1	\$ 92.20
			\$ 5909.80
Less 20% Disc			\$ 1181.96
Total			\$ 4727.84

1278.90

Special Nett Items

1	Rear bumper reverse sensor @ \$200.00	4	\$ 800.00
2	Rear tailgate camera New	1	\$ 800.00
Total			\$ 1600.00

Labour Cost

1	To supply rear end panel inner sealant	\$ 200.00
2	Remove & reinstall reverse sensor	\$ 150.00
3	Remove & reinstall bootlid inner garnish	\$ 150.00
4	Remove, replace & repair consistent to the accident	\$ 1000.00
5	Respray painting	\$ 800.00
Total		\$ 2300.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Grand Total

\$ 21787.40

Total 3233.84

2/5 2.6K

03 Days

26K

04Apr