



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:STACEY NG			Ref: CC4/ASM20005661/Aga3q2 Date: 18/02/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJG 6621M	Veh. Inspected	SLW 9710L
	Policy No.	GA498374	Coverage (\$)	0.00
	Claim No.	S0M02NT2	Excess (\$)	0.00
	Assign From		Assign Date	11/05/2020
2. Vehicle Particulars & Condition				
	Make & Model	MAZDA CX-5	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	JM6KF2W7AJ0155771	Colour	BLUE
	Odometer	31194 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/65 R17	YOKOHAMA	6 mm
	L/H Front Tyre	225/65 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	225/65 R17	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	08/05/2020	Inspection Date	12/05/2020
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	