

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35667

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0388/2020/NS
Date : 11-May-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured veh no : SLE 7318 U

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Woo Suk Jang
Address : 130 Tan Jong Rhu Road
#11-05
Singapore 436918
Telephone : HP +65 92991006
Type of Claim : Third Party Claim
Policy No. : 2000003528
Vehicle No : **SMR 1201 G**
Model Code : Q3 1.4 TFSI S TRONIC
Model / Year : Dec-19
Engine No : CZD 886243
Chassis No : WAUZZZF31L1011104
Mileage : 1944KM
Date In : 11-May-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 10-May-20
Place of Accident : Marina Boulevard And Shears Ave Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMR 1201 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>de</i>	\$	1,946.00
2	FRONT BUMPER CLOSING ELEMENT - LH <i>ms</i>	\$	55.00
3	FRONT BUMPER GRILLE - CENTRE ?	\$	204.00
4	FRONTBUMPER COVER <i>xx</i> ?	\$	48.00
5	FRONT BUMPER GRILLE - LH <i>set</i> ?	\$	104.00
6	FRONT BUMPER CLOSING ELEMENT ?	\$	179.00
7	FRONT BUMPER FRONT SPOILER <i>cm</i>	\$	361.00
8	FRONT BUMPER BRACKET ?	\$	20.00
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>sur</i>	\$	144.00
10	RADIATOR GRILLE ?	\$	1,349.00
11	RADIATOR GRILLE STRIKER PLATE ?	\$	230.00
12	RADIATOR GRILLE BRACKET ?	\$	39.00
13	RADIATOR COVER CAP <i>x</i>	\$	42.00
14	RADIATOR SECURING PLATE ?	\$	31.00
15	AIRCON STICKER <i>me</i>	NEC \$	7.00
16	CAUTION SIGN STICKER <i>me</i>	NEC \$	13.00
17	FRONT BUMPER FOAM FILLER PIECE <i>x</i>	\$	96.00
18	FRONT BUMPER CARRIER <i>x</i>	\$	793.00
19	FRONT BUMPER COVER <i>cm</i>	\$	116.00
20	FRONT BUMPER GUIDE SECTION - LH <i>cm</i>	\$	36.00
SUB TOTAL SPARE PARTS CHARGES		: \$	<u>5,813.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMR 1201 G

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
21	FRONT PARKING AID SENSOR ?			TBC
22	FRONT PARKING AID SEAL RING <i>na</i> ✓	4	\$ 14.00	
23	SIGNAL HORN - LH HIGH TONE X		\$ 129.00	
24	SPRING SHACKLE - LH X		\$ 20.00	
25	FRONT FENDER - LH <i>bum</i> ✓		\$ 1,211.00	
26	FRONT FENDER ATTACHMENT PARTS <i>na</i> ✓		\$ 59.00	
27	FRONT FENDER BRACE - LH <i>bt</i> ✓		\$ 82.00	
28	FRONT FENDER BRACKET - LH <i>bt</i> ✓		\$ 30.00	
29	FRONT FENDER CLOSING ELEMENT - LH <i>de</i> ✓		\$ 31.00	
30	FRONT FENDER INSULATION - LH <i>cut</i> ✓		\$ 40.00	
31	DAMPING - LH UPPER <i>de</i> ✓		\$ 30.00	
32	DAMPING SEAL ?		\$ 34.00	
33	FRONT WHEEL HOUSING LINER - LH <i>TURN</i> ✓		\$ 226.00	
34	WHEEL HOUSING LINER ATTACHMENT PARTS <i>na</i> ✓		\$ 95.00	
35	WHEEL HOUSING LINER COVER - LH ?		\$ 15.00	
36	LED HEADLIGHT - LH <i>cm</i> ✓		\$ 5,263.00	
37	LED WITH HEAT SINK ? <i>diagnose?</i>		\$ 735.00	
38	MAIN LIGHT ELECTRONICS POWER MODULE ? <i>diagnose?</i>		\$ 714.00	
39	HEADLIGHT HOSE - LH X		\$ 23.00	
40	HEADLAMP HOUSING REPAIR KIT - LH <i>cm</i> ✓		\$ 124.00	
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 8,875.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMR 1201 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	LIFT CYLINDER - LH X	\$	198.00
42	LIFT CYLINDER HOSE X	\$	75.00
43	HEADLIGHT MOUNTING - LH CM /	\$	112.00
44	FRONT WHEEL COVER - LH / RH LH-CM / RH-NE 2 /	\$	506.00
45	LOCK CARRIER CM -	\$	1,198.00
46	READY MIX COOLANT ne /	\$	169.00
47	FRONT ALUMINIUM RIM - LH SCR -	\$	893.00
48	TRACK CONTROL ARM X	\$	449.00
49	WHEEL BEARING HOUSING - LH ?	\$	638.00
50	WHEEL BEARING ?	\$	457.00
51	GUIDE JOINT - LH X	\$	135.00
52	COUPLING ROD X	\$	90.00
53	GAS SHOCK ABSORBER X	\$	287.00
54	TRACK ROD X	\$	74.00
55	TIE ROD END - LH X	\$	121.00
56	STEERING GEAR GREASE X	\$	41.00
57	FRONT NO PLATE ?	S/N \$	60.00
58	SUNDRIES ?	\$	400.00
TOTAL SPARE PARTS CHARGES		:	\$ 20,591.00
TOTAL LABOUR CHARGES		:	\$ 13,384.00
GRAND TOTAL		:	\$ 33,975.00

All charges are not inclusive of GST.
Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55, Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMR 1201 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To remove and reinstall aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 /	
3	To remove and renew lhs front wheel suspension assy.	S/N \$ 1,800.00 ?	
4	To dismantle and renew front bumper, lhs front fender and lhs headlight. To repair bonnet. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. <i>fender top support LH (1)</i>	\$ 5,600.00 3250	
5	To respray front bumper, lhs front fender and bonnet. <i>fender top support LH</i>	\$ 3,200.00 2200 2200	
6	To carry out pre-wheel alignment and post-wheel alignment. To renew lhs front rim and carry out wheel alignment.	S/N \$ 520.00 ?	
7	To carry out diagnostic check.	S/N \$ 384.00 192	
TOTAL LABOUR CHARGES		: \$ 13,384.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: *RASUL*

Surveyed Date

: *12/05/2020 @ 1046*

Authorised Date

: *10 days*

Excess Cost

:

Liability

:

Remarks

: *Resy before paint*

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant