

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMR 1201 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>de</i>	\$ 1,946.00	1556.00
2	FRONT BUMPER CLOSING ELEMENT - LH <i>MU</i>	\$ 55.00	43.84
3	FRONT BUMPER GRILLE - CENTRE <i>? XSVL</i>	\$ 204.00	
4	FRONT BUMPER COVER <i>de</i> <i>? XSVL</i>	\$ 48.00	
5	FRONT BUMPER GRILLE - LH <i>de</i> <i>? XSVL</i>	\$ 104.00	
6	FRONT BUMPER CLOSING ELEMENT <i>? XSVL</i>	\$ 179.00	
7	FRONT BUMPER FRONT SPOILER <i>CR</i>	\$ 361.00	288.80
8	FRONT BUMPER BRACKET <i>? XSVL</i>	\$ 20.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH <i>SVL</i>	\$ 144.00	115.20
10	RADIATOR GRILLE <i>? XSVL</i>	\$ 1,349.00	
11	RADIATOR GRILLE STRIKER PLATE <i>? CR</i>	\$ 230.00	183.60
12	RADIATOR GRILLE BRACKET <i>? XSVL</i>	\$ 39.00	
13	RADIATOR COVER CAP <i>X SVL</i>	\$ 42.00	
14	RADIATOR SECURING PLATE <i>? XSVL</i>	\$ 31.00	
15	AIRCON STICKER <i>de</i>	NEC \$ 7.00	5.36
16	CAUTION SIGN STICKER <i>de</i>	NEC \$ 13.00	10.124
17	FRONT BUMPER FOAM FILLER PIECE <i>X SVL</i>	\$ 96.00	
18	FRONT BUMPER CARRIER <i>X SVL</i>	\$ 793.00	
19	FRONT BUMPER COVER <i>CR</i>	\$ 116.00	92.40
20	FRONT BUMPER GUIDE SECTION - LH <i>CR</i>	\$ 36.00	28.64
SUB TOTAL SPARE PARTS CHARGES		: \$ 5,813.00	

Premium Automobiles

Unit 8, Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMR 1201 G

Damaged Parts & Prices
S/Nett Remar

S/N Parts Description

S/N	Parts Description				
21	FRONT PARKING AID SENSOR ? XSVL			TBC	
22	FRONT PARKING AID SEAL RING XX XNN	4	\$	14.00	
23	SIGNAL HORN - LH HIGH TONE XSVL		\$	129.00	
24	SPRING SHACKLE - LH XSVL		\$	20.00	
25	FRONT FENDER - LH bu ✓		\$	1,211.00	968.80
26	FRONT FENDER ATTACHMENT PARTS XX XNN		\$	59.00	
27	FRONT FENDER BRACE - LH bt ✓		\$	82.00	65.60
28	FRONT FENDER BRACKET - LH bt ✓		\$	30.00	23.28
29	FRONT FENDER CLOSING ELEMENT - LH de ✓		\$	31.00	24.56
30	FRONT FENDER INSULATION - LH cut ✓		\$	40.00	31.76
31	DAMPING - LH UPPER de ✓		\$	30.00	23.28
32	DAMPING SEAL ? nee ✓		\$	34.00	26.96
33	FRONT WHEEL HOUSING LINER - LH TORN ✓		\$	226.00	180.40
34	WHEEL HOUSING LINER ATTACHMENT PARTS XX XNN		\$	95.00	
35	WHEEL HOUSING LINER COVER - LH ? CRA ✓		\$	15.00	11.44
36	LED HEADLIGHT - LH CRA ✓		\$	5,263.00	4216.40
37	LED WITH HEAT SINK ? diagnose ? XSVL		\$	735.00	
38	MAIN LIGHT ELECTRONICS POWER MODULE ? diagnose ? NW ✓		\$	714.00	571.20
39	HEADLIGHT HOSE - LH XSVL		\$	23.00	
40	HEADLAMP HOUSING REPAIR KIT - LH CRA ✓		\$	124.00	99.20
SUB TOTAL SPARE PARTS CHARGES			:	\$	8,875.00

Premium Automobiles

55 Ubi Road 1, Singapore 408599
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMR 1201 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
41	LIFT CYLINDER - LH <i>X SUC</i>	\$	198.00
42	LIFT CYLINDER HOSE <i>X SUC</i>	\$	75.00
43	HEADLIGHT MOUNTING - LH <i>CA</i>	\$	112.00 <i>89.20</i>
44	FRONT WHEEL COVER - LH / RH <i>LH-CA / RH-nee</i>	2 / \$	506.00 <i>404.80</i>
45	LOCK CARRIER <i>CA</i>	\$	1,198.00 <i>958.40</i>
46	READY MIX COOLANT <i>nee</i>	\$	169.00 <i>134.72</i>
47	FRONT ALUMINIUM RIM - LH <i>SUC</i>	\$	893.00 <i>714.00</i>
48	TRACK CONTROL ARM <i>X SUC</i>	\$	449.00
49	WHEEL BEARING HOUSING - LH <i>? X SUC</i>	\$	638.00
50	WHEEL BEARING <i>? X SUC</i>	\$	457.00
51	GUIDE JOINT - LH <i>X SUC</i>	\$	135.00
52	COUPLING ROD <i>X SUC</i>	\$	90.00
53	GAS SHOCK ABSORBER <i>X SUC</i>	\$	287.00
54	TRACK ROD <i>X SUC</i>	\$	74.00
55	TIE ROD END - LH <i>X SUC</i>	\$	121.00
56	STEERING GEAR GREASE <i>X NN</i>	\$	41.00
57	FRONT NO PLATE <i>? X SUC</i>	S/N \$	60.00
58	SUNDRIES <i>? nee</i>	\$	400.00 <i>14.08</i>
TOTAL SPARE PARTS CHARGES		:	\$ 20,591.00
TOTAL LABOUR CHARGES		:	\$ 13,384.00
GRAND TOTAL		:	\$ 33,975.00

All charges are not inclusive of GST.
Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMR 1201 G

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall fron wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To remove and reinstall aircon condenser, charged air cooler, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,400.00 /	
3	To remove and renew lhs front wheel suspension assy.	S/N \$ 1,800.00 ?Xm	
4	To dismantle and renew front bumper, lhs front fender and lhs headlight. To repair bonnet. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed. <i>fender top support LH (1)</i>	\$ 5,600.00 3250 /	
5	To respray front bumper, lhs front fender and bonnet. <i>fender top support LH</i>	\$ 3,200.00 2200 /	
6	To carry out pre-wheel alignment and post-wheel alignment. To renew lhs front rim and carry out wheel alignment.	S/N \$ 520.00 ? 260 /	
7	To carry out diagnostic check.	S/N \$ 384.00 192 /	
TOTAL LABOUR CHARGES		: \$ 13,384.00	

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0388/2020/NS 19-May-20 Glory Tan 1 of 1 SMR 1201 G Q3 1.4 TFSI S TRONIC
Quantity	Description	Unit Price	Amount
Parts			
1	Headlight socket LHS - cra	\$ 15.00	\$ 11.60
2	A-pillar fender mounting LHS - mis	\$ 61.00	\$ 48.32
3	Headlight mounting RHS - cra	\$ 112.00	\$ 89.20
			<u>\$ 149.12</u>
Labours			
1	To cut out and weld back A-pillar fender mounting LHS	\$ 1,000.00	\$ 500.00
2	To respray A-pillar fender mounting LHS	\$ 1,000.00	\$ 550.00
3	To remove and reinstall dashboard to facilitate A-pillar fender mounting LHS renewal.	s/n \$ 2,800.00	\$ 2,800.00
TOTAL		<u>\$ 4,988.00</u>	<u>\$ 3,999.12</u>

For Premium Automobiles Pte Ltd

Authorised Signature

p/p = 22,657.28
15 repair days

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Rasul
: 12/05/2020 @ 1046
: 10 days + 5 days = 15 days
: Resy before paint

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant