

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



Supplementary

Estimate No. : **b1 55108**
Date Estimated : **11/05/2020**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -

Darren Ng Yew Huat
1 Paya Lebar Crescent
#03-12 Tangerine Grove

Singapore 536019

- ACCOUNT - 135

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMN3805Y	WBA5R12070AE79946	28/03/2019	330i LIM	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
# To remove and reconnect all electrical components, control units, wirings systems at the engine bay and conduct tests for proper function.	451.00		451.00 ✓
# To replace exch turbo charger including conduct check for leak and proper function.	765.00		765.00 ✓
# To replace starter motor including conduct check for proper function.	451.00		451.00 ✓
# To supply BWM engine oil - 5.25 litres	173.25		173.25 ✓
# Sundries	150.00		150.00 ✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# DOWEL PIN 4X16MM	3.05	2.00		6.10
# EXCH TURBOCHARGER W EXHAUST MANIFOL	4,065.80	1.00		4,065.80
# SET OF SMALL PARTS	21.65	1.00		21.65
# GASKET RING	23.75	1.00		23.75

SUPPLEMENTARY ITEMS

Total Labour :	1,990.25
Total Parts :	4,093.55
Total Labour & Parts :	6,107.55 6,083.80
Deduction for Excess :	750.00
Total Repair Costs less Excess:	5,333.80
GST @7%:	373.37
Grand Total :	5,707.17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____