



華平汽車服務 HWA PENG AUTO SERVICE (1996)

70 Woodlands Industrial Park E9 Singapore 757836

TEL: 6365 6100 FAX: 6365 6101

Spray Painting • Panel Beating • Body Repair • Engine Tuning • Towing Service • Insurance Claim • L.T.A. Inspection Service
Co. Reg 52823719E

ESTIMATE REPORT

Lin Zhi Hao
C/o 70 Woodlands Industrial Park E9
Singapore 757836

Vehicle Number : SKF2433J
Make And Model : Volkswagen Touran
Date of Accident : 03 April 2020

S/No	Parts	QTY	Unit Price	List Price
1	Rear bumper ✓ DD	1		\$ 1,201.40
2	Rear bumper lower skirt × NN	1		\$ 462.00
3	Rear bumper side retainer LH & RH ✓ BR	2	\$ 90.00	\$ 180.00
4	Rear bumper centre retainer ✓ BR	1		\$ 129.10
5	Rear bumper reinforcement × NN	1		\$ 520.00
6	Rear bumper reinforcement bracket LH & RH × NN	2	\$ 141.00	\$ 171.00
7	Rear bumper reflector LH & RH (LH) ✓ CUT	2 1	\$ 65.00	\$ 130.00
8	Rear bumper tow cover × NN	1		\$ 48.00
				\$ 2,841.50
				Less 10% \$ 284.15
Total				\$ 2,557.35

Special Nett Item

9	Rear bumper clips ✓ NEC		\$ 30 ✓	60.00
10	Reverse sensor ✓ BR		\$ 250 ✓	300.00
Total				\$ 360.00

Labour & Misc Charges

To dismantle, replace & panel beating affected parts for rear portion.	\$ 300 ✓	600.00
To spray paint on affected areas for rear portion.	\$ 300 ✓	600.00
To remove/replace reverse sensors.	\$ 30 ✓	100.00
To check wiring.	\$ 30 ✓	50.00
To perform system diagnostic & reset ECU.	\$	400.00 ×
Total	\$	1,750.00

Grand Total : \$ 4,667.35

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Steve (LKK)
Without Prejudice
3 repair days
L/S
Resurvey After Spray

Acknowledged by Repairer

Signature: _____

Date: _____