



Automobile Integrated Management Pte Ltd
Co. & G.S.T. Reg no. 201605297G
Office: 28 Sin Ming Lane #07-147 Midview City Singapore
573972
Workshop: 23 Kaki Bukit Ave 5 #04-01 (South Wing) Singapore
415933
Email: automim.claim@gmail.com Tel: 9119 8371

Not Adm
den
w/s 85500/
SLY.
Thy M. Hh
Rgn.
12/5/20

ESTIMATE

Our ref: AC2020032/TP/SLD7019M-07.05.2020

Vehicle number: SLD7019M

Vehicle Made & Model: HONDA VEZEL

Item	Qty	List Items	Amount \$
1	1	Tailgate <i>Body 20 953</i>	1,209.10
2	1	Tailgate outer garnish <i>11</i>	341.20 X
3	1	Tailgate emblem "H" <i>11</i>	32.20 X
4	1	Tailgate emblem "VEZEL" <i>neu</i>	45.90
5	2	Tailgate lamps - L/R @ 311.80 <i>CRU 276.90 x 2 = 553.80</i>	623.60
6	1 set	Tailgate glass moulding <i>neu</i>	112.20
7	1	Tailgate inner lock <i>twi/3rd 198.50</i>	204.10
8	1	Tailgate inner trim <i>re/twi</i>	310.60
9	1	Tailgate inner pull pocket <i>11</i>	86.60 X
10	1	Tailgate lock striker <i>11</i>	28.60 X
11	1	Tailgate w/strip <i>twi</i>	114.10
12	2	Tailgate dampers - L/R @ 108.50 <i>11</i>	217.00 X
13	2	Tailgate hinges @ 74.10 <i>11</i>	148.20 X
14	2	Tailgate stoppers @ 12.20 <i>11</i>	24.40 X
15	2	Taillamps - L/R @ 381.90 <i>CRU</i>	763.80
16	1	Rear bumper <i>D.S</i>	761.60
17	2	Rear bumper reflectors - L/R @ 89.60 <i>11</i>	179.20 X
18	2	Rear bumper sides - L/R @ 241.60 <i>11</i>	483.20 X
19	2	Rear bumper side retainers - L/R @ 48.60 <i>11</i>	97.20 X
20	10	Rear bumper clips @ 4.50 <i>neu</i>	45.00
21	1	Rear end panel <i>Body 20 514</i>	560.90
22	1	Rear end panel inner trim <i>twi 128.60</i>	182.90
23	1	Rear exhaust silencer <i>11</i>	688.10 X
24	1	Rear exhaust insulator <i>11</i>	70.80 X
25	2	Rear exhaust mountings @ 18.60 <i>11</i>	37.20 X
26	1	Rear floor board <i>wagnd/700 315.00</i>	380.60
27	1	Rear floor tray <i>Spice 700</i>	391.20
28	1	Rear floor panel <i>11</i>	911.40 X
29	1	Rear floor panel undercover <i>de/wagnd</i>	241.20
30	2	Rear fender inner trims - L/R @ 290.80 <i>11</i>	581.60 X
31	1	Rear smart keyless antenna <i>11</i>	180.90 X
32	1	Rear smart keyless buzzer <i>11</i>	192.90 X
33	2	Rear fender wheel arch garnishes - L/R @ 241.20 <i>M/S twi</i>	482.40 <i>IPC</i>
Sub-total			10,729.90
Less 20%			2,145.98
Total List			8,583.92

86897

Vehicle number: SLD7019M

Vehicle Made & Model: HONDA VEZEL

Special Nett Items

34	1 set	Rear reverse sensor	280.00	200
35	1	Rear reverse camera	450.00	350
36	1 set	Tailgate glass sealant	80.00	40
37	1 set	Tailgate glass foam tape	65.00	30
Total Special Nett			875.00	

Labour charges

38	To check rear electrical wiring	50.00	20
39	To remove, refix tailgate glass	180.00	120
40	To remove, refix rear reverse camera / sensor	80.00	50
41	To remove, refix rear exhaust systems	100.00	X
42	To respray undercoating	120.00	60
43	To remove, refix rear interior trims to assist repair	120.00	80
44	Reinstall tailgate electrical & mechanical to new tailgate	180.00	60
45	To respray painting and etc	1,400.00	900
46	Panel beating, cut, weld remove & replacing above parts	1,500.00	700
Total Labour		3,730.00	

P - 451.76
S.N - 440
L - 1990

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

13,188.92

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: