

mates on Miscellaneous Items

Qty	Particulars	Amount
<u>Miscellaneous Items</u>		
1	Engine coolant / Acc.	40.00
1	Front number plate / PT	15 45.00
1	Front windscreen inner rubber seal / Acc.	42 95.00
1	Front windscreen sealant /	20 80.00
1	LH front tyre /	60 180.00
1	RH front tyre /	60 180.00
1	RH rear outer tyre / Cat.	60 180.00
1	Towing (to flip lorry upright and tow to workshop) - Bill	NN 350.00
1	Used front cabin /	6000 8,000.00
1	Used LH front control arm / BT	600.00
1	Used LH front knuckle arm / BT	300.00
1	Used LH front upper arm / BT	250.00
1	Used LH front wheel rim / BT	80 200.00
1	Used RH drive shaft / NN	250.00
1	Used RH front control arm / BT	600.00
1	Used RH front knuckle arm / BT	300.00
1	Used RH front upper arm / BT	250.00
1	Used RH front wheel rim / Cat.	80 200.00
1	Used RH rear wheel rim / BT	80 200.00
Sub Total (S\$)		12,300.00

Estimates on Labour

No Particulars

Labour Items

		Lab Type	Amount
1	To remove and install dashboard and centre console, including instrument panel, radio, climate control module	New	200 200.00
2	To remove and reinstall air con blower box, air con condenser, dryer, aluminium pipes, valves and reinstall components and vacuum and charge refrigerant R134a and check for leakage and full functionality	New	120 180.00
3	To remove and reinstall front windscreen and conduct water leak test	New	✓ 120.00
4	To repair and reshape LH side cargo aluminium roof top, and replace aluminium panel	NN New	✗ 380.00
5	To remove and install rear differential and RH rear drive shaft. To check for damage and replace damaged parts	New	200 380.00
6	To remove and check RH & LH front suspension system, front cross member and replace damaged parts	New	500 550.00
7	To perform computerised wheel alignment	New	60 80.00
8	To remove and install Roof lining, front seats, front door trims, and pillar trims	New	80 250.00
9	To remove and check engine, gearbox, radiator, engine & gearbox mountings, intake and exhaust manifold & for damage and reinstall components and check engine running functionality	80 New	→ 320.00
10	To remove front damaged parts, to replace front cabin, and cut out damaged parts, to straighten out front chassis, to repair and reshape front chassis member, to remove and replace all front cabin parts and adjust body panel alignment	New	1000 1,200.00
11	To disconnect wire harness to facilitate repairs and check for damage and reconnect wiring system and check for full functionality. To focus headlamp	New	30 120.00
12	To spray paint affected front and rear and inner damaged portion inclusive of preparatory works and material	New	600 1,800.00

Gross Labour Cost (S\$) 5,660.00

S & H Motor Pte Ltd/YP620E/11/05/2020 18:08. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Workshop: 180 Sin Ming Drive #07-02 Sin Ming AutoCity, Sin Ming EPF722 Tel: 6453 4730 Fax: 6457 1931 E-mail: shmotor@singnet.com.sg
Co. Reg. No. 198701222K GET Reg. No. M2-007626B-3

14 Days
Unpym repair
After repair
Not Authorised.
Excess \$700.

Eric Qiang
82880282

Eric Qiang @ lkk auto. com
12/5/2020.

LK Auto City/Shop hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary part(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: