

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
GST:201001158E RCB NO:201001158E

SLX993R  
TP/A 6

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
TEL: 64193000 FAX: 64153727  
ATTN: Motor Claim Department

WS Ref: TP/AIG/YS  
Claim Type: Third Party  
Accident Date: 06/05/2020  
TP Veh Reg No: SJN1307S

Estimate No: ES2090404/YISHUN  
Date: 18 May 2020  
Policy No: 5109867777  
Veh Reg No: SLX993R  
Make/Model: MERCEDES BENZ CLA  
200 (R185 SR)  
Chassis No: WDD1173432N051713  
Engine No: 27091030294181  
Reg. Date: 20/12/2013

## Estimate Repair Cost to Vehicle No :SLX993R

| Description                                                                                      | U/Price  | Quantity | List Price<br>S\$    | Amount<br>S\$ |
|--------------------------------------------------------------------------------------------------|----------|----------|----------------------|---------------|
| <b>Net Price</b>                                                                                 |          |          |                      |               |
| 1 REAR BUMPER                                                                                    | 1,625.00 | 1 PC     | 1,625.00             | ✓             |
| 2 REAR BUMPER RH SIDE INNER GARNISH                                                              | 57.00    | 1 PC     | 57.00                | ✓             |
| 3 REAR BUMPER RH REVERSE SENSOR                                                                  | 188.00   | 1 PC     | 188.00               | ✓             |
| 4 REAR BUMPER CENTRE LOWER SKIRT                                                                 | 245.00   | 1 PC     | 245.00               | ✓             |
|                                                                                                  |          |          | 2,115.00             |               |
|                                                                                                  |          | Less 10% | 211.50               | 1,903.50      |
| <b>Labour</b>                                                                                    |          |          |                      |               |
| 5 REMOVE & REFIX REAR BUMPER ASSY,KNOCK & REPAIR<br>REAR BUMPER REINFORCEMENT & REALIGN THE SAME | 380.00   | 1 LA     | 380.00               | 280           |
| 6 PUTTY & RESPRAY ON REAR BUMPER,REAR<br>REINFORCEMENT                                           | 480.00   | 1 LA     | 480.00               | 350           |
| 7 REMOVE & REFIX REVERSE SENSOR & RESET SYSTEM                                                   | 50.00    | 1 LA     | 50.00                | ✓             |
|                                                                                                  |          |          | 910.00               | 910.00        |
|                                                                                                  |          |          | Total                | S\$ 2,813.50  |
|                                                                                                  |          |          | Add GST @ 7%         | 196.95        |
|                                                                                                  |          |          | Total Amount Payable | S\$ 3,010.45  |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE