

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20005686/KEA3Q2
Date: 28/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900151417
Claimant Vehicle No :	SJV191Y	Insured Vehicle No :	GBJ7584J
Date of Loss:	08/05/2020	Nature of Claim:	TP
		Claim No:	4779669341SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJV191Y		
Make & Model:	MERCEDES-BENZ C43, 3.0 AMG 4MATIC CAB (R18 LED) (A)	Engine No:	27682330656305
Reg. Date:	26/06/2018 (Man. Year: 2017)	Chassis No:	WDD2050642R329836
Colour:	White	Odometer:	21282 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	225/40R19	Rear Tyre Size:	255/35 ZR19
Front Left Side:	Pirelli 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Pirelli 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,666.13	6,550.13	1,116.00	14.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,670.00	1,110.00	560.00	33.53
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	9,336.13	7,660.13	1,676.00	17.95
+ GST 7.00/7.00% (S\$)	653.53	536.21	117.32	17.95

Nett Amount (S\$)	9,989.66	8,196.34	1,793.32	17.95
+ Loss of Use (4.0 x S\$120.00/day) (S\$)		480.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		8,678.34		

INSPECTION

Date of Assignment: 19/05/2020

Date Inspected: 19/05/2020

Estimated Period of Repair: 4.0 days

Inspected At: Optima Werkz Pte Ltd (HQ)
9A Serangoon North Ave 5
Singapore 554500

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Mtg Cracked	1,910.00 FL	*1,720.00 FL
2	12		*FRONT BUMPER CLIPS	Necessary	78.00 FL	*78.00 FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Cracked	52.00 FL	*52.00 FL
4	1		*FRONT BUMPER INNER GUIDE RH	Serviceable	90.00 FL	*- FL
5	1		*FRONT BUMPER REINFORCEMENT	Repair	470.00 FL	*- FL
6	1		*FRONT FENDER RH	Bent	995.00 FL	*980.00 FL
7	1		*FRONT FENDER EMBLEM RH	Necessary	222.00 FL	*222.00 FL
8	1		*FRONT SUPPORT PANEL TIE BAR	Distorted	363.00 FL	*363.00 FL
9	1		*FRONT FENDER INNER LINER RH	Cracked	270.00 FL	*270.00 FL
10	10		*FRONT FENDER INNER LINER CLIPS RH	Necessary	55.00 FL	*55.00 FL
11	1		*FRONT HEADLAMP ASSY RH	Mtg Cracked	3,505.00 FL	*3,150.00 FL
12	1		*FRONT HEADLAMP LOWER BRACKET RH	Repair	120.00 FL	*- FL
13	1		*FRONT BUMPER LOWER LIP GARNISH COVER RH	Mtg Cracked	305.00 FL	*305.00 FL
14	1		*FRONT BONNET (NPA)	Repair	0.00 FL	*- FL
15	1		*FRONT BUMPER REINFORCEMENT SUPPORT BRACKET RH	Bent	82.92 FL	*82.92 FL
					Sub Total (\$\$)	8,517.92
					- List Item Discount on L Items 10.00/10.00% (\$\$)	851.79
					Total Parts (\$\$)	7,666.13

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE,REPLACE,REPAIR,REFIX & READJUST FRONT ACCIDENT AREAS & ETC	New	600.00	450.00
2	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER,FRONT BONNET,FRONT FENDER RH & ETC	New	800.00	600.00
3	LABOUR CHARGES TO REMOVE,REFIX & REPAIR FRONT PARKING SENSOR & ETC.TO EFFECT REPLACE OF FRONT BUMPER	New	120.00	60.00
4	TO DIAGNOSIS FAULTY CODE & RESET MEMORY	New	150.00	0.00
Gross Labour Cost (S\$)			1,670.00	1,110.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >