

Date: 12.05.2020
Vehicle No: SJV191Y
Model: MERCEDES BENZ C43 AMG
Chassis: WDD2050642R329836-2017
Reg.Year: 2018

Third Party Insurer: AIG
Third Party Veh No: GBJ7584J
Date of Accident: 08.05.2020

Not Authorised
Resurvey B & paint 4 days

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1	<i>mg cm</i>	\$1,910.00
2	FRONT BUMPER CLIPS	12	\$6.50	<i>re</i> \$78.00
3	FRONT BUMPER SIDE RETAINER RH	1		<i>cm</i> \$52.00
4	FRONT BUMPER INNER GUIDE RH	1		\$90.00
5	FRONT BUMPER REINFORCEMENT	1		<i>R</i> \$470.00
6	FRONT FENDER RH	1		<i>R</i> \$995.00
7	FRONT FENDER EMBLEM RH	1		<i>re</i> \$222.00
8	FRONT SUPPORT PANEL TIE BAR	1		\$363.00
9	FRONT FENDER INNER LINER RH	1		<i>cm</i> \$270.00
10	FRONT FENDER INNER LINER CLIPS RH	10	\$5.50	<i>re</i> \$55.00
11	FRONT HEADLAMP ASSY RH	1	<i>mg cm</i>	\$3,505.00
12	FRONT HEADLAMP LOWER BRACKET RH	1		\$120.00
13	FRONT BUMPER LOWER LIP GARNISH COVER RH	1		\$305.00
14	FRONT BONNET	1		REPAIR
SUB TOTAL				\$8,435.00
LESS 10%				-\$843.50
PARTS TOTAL				\$7,591.50

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REPAIR, REFIX & READJUST FRONT ACCIDENT AREAS & ETC.

450
\$600.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRONT BONNET, FRONT FENDER RH & ETC.

600
\$800.00

LABOUR CHARGES TO REMOVE, REFIX & REPAIR FRONT PARKING SENSOR & ETC. TO EFFECT REPLACE OF FRONT BUMPER.

60
\$120.00

TO DIAGNOSIS FAULTY CODE & RESET MEMORY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

150
\$150.00

LABOUR TOTAL \$1,670.00

TOTAL \$9,261.50

TingAn

Acknowledged by Repairer
Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

