

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	08/05/2020
Vehicle Reg. No.:	SHC2567H	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Vehicle Reg. Date:	12/03/2019
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	G4LEJU191966	Chassis No:	KMHC851CVKU141497
Odometer:	0 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	8		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS	Amount
Parts	11,838.12
Miscellaneous Items	11.00
Labour	3,270.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	15,119.12
+ GST 7.00% (S\$)	1,058.34
Nett Amount (S\$)	16,177.46

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 May 2020)	
Parts:	N/A	HYUNDAI AE IONIQ HEV DCT 1.6 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	ComfortDelGro Engineering Pte Ltd/SHC2567H/19/05/2020 13:00	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BOOT LID <i>DD</i>	20.00	0.00	*2,480.40 FL
2	1		*BOOT LID RUBBER <i>xun</i>	20.00	0.00	*187.40 FL
3	2		*BOOT LID HINGE LH/RH <i>xun</i>	20.00	0.00	*142.60 FL
4	2		*BOOT LID ABSORBER LH/RH <i>xun</i>	20.00	0.00	*173.40 FL
5	1		*BOOT LID EMBLEM <i>hec</i> X NN	20.00	0.00	*28.00 FL
6	1		*BOOT LID EMBLEM- HYB <i>hec</i>	20.00	0.00	*24.30 FL
7	1		*BOOT LID EMBLE- IONIQ <i>hec</i>	20.00	0.00	*31.30 FL
8	1		*BOOTLID HANDLE <i>xun</i>	20.00	0.00	*31.80 FL
9	2		*BOOTLID LAMP LH/RH <i>LH only scr</i> RH X NN	20.00	0.00	*1,588.80 FL
10	1		*BOOTLID TRIMBOARD <i>xun</i>	20.00	0.00	*259.70 FL
11	10		*BOOTLID TRIMBOARD CLIP 10PCS <i>xun</i>	20.00	0.00	*11.00 FL
12	1		*BOOTLID GLASS UPPER, MOULDING <i>hec</i> X NN	20.00	0.00	*186.30 FL
13	1		*REAR BUMPER <i>ms</i>	20.00	0.00	*459.40 FL
14	1		*REAR BUMPER REINFORCEMENT <i>cra</i>	20.00	0.00	*394.60 FL
15	2		*REAR BUMPER REINFORCEMENT BRACKET LH/RH XXXXXXXX <i>DD</i>	20.00	0.00	*376.20 FL 138.10
16	1		*REAR BUMPER CENTRE MOULDING ASSY <i>cra</i>	20.00	0.00	*451.25 FL
17	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY <i>scr</i>	20.00	0.00	*47.50 FL
18	1		*REAR BUMPER RETAINER <i>hec</i>	20.00	0.00	*85.80 FL
19	10		*REAR BUMPER CLIPS <i>hec</i>	20.00	0.00	*22.00 FL
20	1		*REAR BUMPER CENTRE UNDER COVER ms <i>cra</i> X NN	20.00	0.00	*123.85 FL
21	1		*REAR BUMPER REAR TOW COVER <i>ms</i>	20.00	0.00	*98.80 FL
22	2		*REAR BUMPER REFLECTOR LAMP LH/RH <i>ms</i>	20.00	0.00	*165.80 FL
23	1		*REAR BUMPER REVERSE LIGHT <i>ms</i>	20.00	0.00	*328.60 FL
24	2		*REAR LICENCE LAMP LH/RH <i>ms</i>	20.00	0.00	*170.60 FL
25	2		*TAIL LAMP LH/RH <i>xun LH SCR</i> RH X NN	20.00	0.00	*740.80 FL 870.40
26	1		*REAR PANEL <i>bucc</i>	20.00	0.00	*532.00 FL
27	1		*REAR PANEL GARNISH <i>xun</i>	20.00	0.00	*346.80 FL
28	1		*REAR SPARE TYRE PANEL <i>xun</i>	20.00	0.00	*892.50 FL
29	1		*REAR TRAY TOOL BOX RH <i>xun</i>	20.00	0.00	*675.30 FL
30	1		*REAR TRAY TOOL BOX LH <i>xun</i>	20.00	0.00	*693.20 FL
31	1		*REAR EXHAUST SILENCER <i>DD</i>	20.00	0.00	*943.60 FL
32	1		*REAR EXHAUST PIPE CENTRE <i>? XX</i>	20.00	0.00	*578.60 FL 689.50
33	1		*REAR EXHAUST PIPE HANGER <i>xun</i>	20.00	0.00	*29.20 FL
34	1		*BOOTLID COMFORT LOGO & TEL NO STICKER <i>hec</i>	0	0.00	*35.00 FS
35	1		*BOOTLID COMFORT CABLINK TEL NO STICKER <i>hec</i>	0	0.00	*30.00 FS
36	1		*REAR NO PLATE & HOLDER XXXXXXXX NN	0	0.00	*60.00 FS
37	1		*REAR BUMPER RUBBER MAT <i>hec</i>	0	0.00	*50.00 FS
38	1		*REAR BUMPER REVERSE SENSOR <i>ms</i>	0	0.00	*180.00 FS
39	1		*REAR WINDSCREEN SEALANT <i>hec</i>	0	0.00	*46.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,697.40
- List Item Discount on L Items (S\$)	2,859.28
Total Parts (S\$)	11,838.12

ComfortDelGro Engineering Pte Ltd/SHC2567H/19/05/2020 13:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New \$960	1,300.00
2	SPRAY PAINTING	New \$600	1,000.00
3	WIRING	New \$50	90.00
4	TUFF KOTE	New \$60	120.00
5	TOWING FEE	New XX	60.00
6	REMOVE/REFIX REAR WINDSCREEN	New \$100	120.00
7	REMOVE/REFIX REAR EXHAUST PIPE SYST	New \$70	90.00
8	REMOVE/REFIX REAR REVERSE SENAOR	New \$60	90.00
9	DIAGNOSTIC & RESST TO ERASE FAULT CODE	New XXXX	400.00
Gross Labour Cost (\$\$)			3,270.00

ComfortDelGro Engineering Pte Ltd/SHC2567H/19/05/2020 13:00. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Ram (UK)
19/05/2020 1450
ram@uk.com
88622778
Self print photo
Resurvey Required
10 repair days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: