



新福德車廠私人有限公司

NEW HOCK TECK MOTOR PTE. LTD.

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: admin@nhtmotor.com

Website: www.nhtmotor.com

Tel: 6747 9241

Fax: 6741 7276

UEN: 201718370K

12/05/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP MS16.

Denise.

Accident date: 11/05/2020

Estimated repair cost for vehicle no: SGM4281C TOYOTA WISH 1.8 A 06'

CHASSIS: ZNE100324586

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented.</i>		\$1,315.20	1248
2	2	Rear Boot Lid Hinge <i>neu</i>	\$141.40	\$282.80	+
3	2	Rear Boot Lid Shock Absorber <i>neu</i>	\$371.80	\$743.60	+
4	1	Rear Boot Lid Emblem Logo <i>neu</i>		\$51.10	✓
5	1	Rear Boot Lid Wish Chrome Moulding <i>Repld</i>		\$274.40	✓
6	1	Rear Boot Lid Number Plate <i>neu</i>		\$50.00	+
7	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$374.40	✓
8	1	Rear Boot Lid Inner Rubber <i>neu</i>		\$381.90	x.
9	1	Rear Boot Lid Inner Trim Board <i>crushed</i>		\$781.40	485
10	1	Rear Boot Lid Inner Center Trim Cover <i>Not nec</i>		\$282.60	x.
11	2	Rear Boot Lid Inner Side Trim Cover <i>neu</i>	\$122.80	\$245.60	+
12	1	Rear Boot Lid Windscreen Seal <i>3pc</i>		\$125.00	✓
13	2	Rear Boot Lid Windscreen Moulding	\$68.00	\$136.00	✓
14	1	Rear Boot Lid Reverse Camera (Special Nett) <i>Not nec</i>		\$680.00	x.
15	2	Rear Tail Lamp <i>int</i>	\$387.40	\$774.80	✓
16	4	Rear Tail Lamp Clip <i>neu</i>	\$8.00	\$32.00	10.
17	1	Rear Bumper <i>Repld</i>		\$625.20	541
18	8	Rear Bumper Clip <i>neu</i>	\$6.50	\$52.00	30.
19	2	Rear Bumper Side Retainer <i>neu</i>	\$132.10	\$264.20	125
20	2	Rear Bumper Side Reflector <i>neu</i>	\$141.40	\$282.80	+
21	1	Rear Bumper Reverse Sensor (Special Nett) <i>Damaged</i>		\$380.00	200(SN)
22	1	Rear End Panel Outer <i>Dented.</i>		\$519.80	✓
23	1	Rear End Panel Inner <i>Repair</i>		\$780.50	x.
24	1	Rear End Panel Top Garnish <i>Repld</i>		\$375.40	289.
26	2	Rear Fender Inner Trim Board	\$471.40	\$942.80	x
27	16	Rear Fender Inner Trim Board Clip <i>Not</i>	\$6.50	\$104.00	+
28	2	Rear Fender Cowling <i>neu</i>	\$172.20	\$344.40	+
29	12	Rear Fender Cowling Clip	\$6.50	\$78.00	+
30	2	Rear Fender Air Duct	\$89.60	\$179.20	+

498350

373762

SN: 200

Subtotal :- \$11,459.10Labour charges

To remove & refit cushion & trim board	\$280.00 80
To remove & refit reverse sensor	\$100.00 50
To remove & refit reverse camera	\$180.00 50
To remove & refit rear windscreen	\$120.00 ✓
Gum	\$50.00 ✓
To check wiring	\$100.00 30
Tuff kote	1730 \$150.00 50
Towing fee	\$150.00 X
Panel beating	\$1,400.00 700
Spray painting	\$1,400.00 600

Subtotal :- \$3,930.00Total:- \$15,389.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 566762

L/S: 45K

05 Days

05/07/20
45K