

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHD 9086C - AXA

Not Authored
61 Rmp & 3500h

ROEL

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHD 9086C - ROEL
 JTDGJ20W105003343
 TOYOTA
 WISH 2.0 BI-FUEL
 23.06.16
AXA

PART		LIST	
1	1	Front Bumper	\$ CM 585.36 ✓
2	1	Front Bumper Lower Absorber	\$ Sn 130.00 X
3	1	Front Bumper Reinforcement	\$ R 318.11 X
4	1	Front Bumper Side Support LH	\$ Sn 76.20 X
5	1	Front Bumper Side Support RH	\$ Sn 76.20 X
6	1	Front Bumper Retainer RH	\$ D17 102.00 —
7	1	Front Bumper Retainer LH	\$ Sn 102.00 X
8	1	Front Bumper Bracket RH	\$ R 108.00 X
9	1	Front Bumper Bracket LH	\$ R 108.00 X
10	1	Front Bumper Fog Lamp RH	\$ Sn 208.00 X
11	1	Front Bumper Fog Lamp Outer Chrome RH	\$ M17 190.00 —
12	1	Front Bumper Fog Lamp Grille RH	\$ M17 150.00 —
13	1	Front Bumper Fog Lamp LH	\$ M17 208.00 ✓
14	1	Front Bumper Fog Lamp Outer Chrome LH	\$ M17 190.00 —
15	1	Front Bumper Fog Lamp Grille LH	\$ M17 150.00 —
16	1	Front Headlamp RH	\$ Bn 672.00 ✓
17	1	Front Headlamp LH	\$ Sn 672.00 X
18	1	Front Support Panel Assy	\$ R 1,222.32 X
19	1	Front Brace Panel	\$ R 95.49 X
20	1	Bonnet	\$ Bn 1,019.16 ✓
21	1	Bonnet Under Weatherstrip Seal	\$ Sn 71.99 X
22	1	Bonnet Centre 'TOYOTA' Logo Badge	\$ Rn 115.44 ✓
23	1	Front Fender LH	\$ R Bn 837.60 ✓ X
24	1	Front Fender Liner LH	\$ Sn 369.14 X
25	1	Front Fender RH	\$ Bn 837.60 ✓
26	1	Front Fender Liner RH	\$ Sn 369.14 X
27	1	Radiator Assembly	\$ Sn 2,268.24 X
28	1	Radiator Grille	\$ Sn 462.48 X

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST 63 SINGAPORE 569111
 TEL NO.6287 6666 FAX NO.6257 1330
 CO/GST REG NO.201019626G
SHD 9086C - AXA

ROEL

- | | | | | |
|----|---|------------------|----|----------------------|
| 29 | 1 | Radiator Cowling | \$ | <i>Sn</i> 221.73 X |
| 30 | 1 | Aircon Condenser | \$ | <i>Sn</i> 1,375.50 X |

TOTAL	\$	13,311.70
25%	\$	3,327.93
	\$	9,983.78

Specical Nett

- | | | | | |
|---|-------|----------------------------|----|-----------------------------|
| 1 | 1 Set | Front Bumper Fastener Clip | \$ | <i>nn</i> 40.00 ✓ |
| 2 | 1 | CNG Sticker | \$ | <i>nn</i> 30.00 <i>15sn</i> |
| 3 | 1 Set | Front Fender Liner Clip LH | \$ | <i>nn</i> 30.00 X |
| 4 | 1 Set | Front Fender Liner Clip RH | \$ | <i>nn</i> 30.00 X |
| 5 | 2 | Bonnet Stopper | \$ | <i>Sn</i> 9.60 X |
| 6 | 1 Set | Radiator Grille Clip | \$ | <i>nn</i> 18.00 X |
| 7 | 1 | Front Licence Plate | \$ | <i>Sn</i> 50.00 X |

TOTAL	\$	207.60
TOTAL PARTS	\$	10,191.38

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$ 2,800.00 *500*

To Check Electrical Lighting Concerned.

\$ 120.00 *200*

To Rust-Proofing Of The Affected Areas.

\$ 200.00 *600*

Putty And Spray Painting Of The Affected
 Portion.

\$ 2,700.00 *600*

To check ABS brake efficiency, final checking
 and testing.

\$ *nn* 380.00 X

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to final approval
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary repair to the resurveyed and is subject to final approval from insurance company

TOTAL \$ **6,200.00**
Over All Total \$ **16,391.38**
Total Repair Days
 acknowledged by Repairer
 signature:

10 DAYS
3 days