	62005695/693
PRS	ASSIGNMENT
From: Date:	Veh No: SL 8 2061H Yr Regn: 30/3/16
Estimated Cost:	Type: M.Ca / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
DD (TP) WS / TP RES / OD RES / EVA / INV / MY	Truck / Trailer or
o Inspect Vehicle No:	Make: Toyota Altis c.c 1598
at Workshop m/s	Colour A/C: Insured / Std / NI / NA
f	Sp.Reading Sp.Reading T/Radio: Insured / Std / NI / NA
sured:	Eng/No:
olicy No.	C/No: MR 053REH 104546.321
laims No.	Gen. Cond: Good / Fair / Poor / Burnt
um Insured: Excess:	Steering: Interder / Jammed / Leaked / Burnt or
(Client's Record)	
lake of Veh;	Summer / Bounced / Bullit of
(Policy Condition)	Tyre Size: F: 195/50 R/6
amada Tha and had	O/S RS / OUN / EXNOVA / OV / EX
repair at the time of inspection.	D/S BS / OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO OF
al. or Market Value;	
PAC Accident Rport Consistent? : Yes or No	R/Bal. Rear
IA / PR Seen: Consistent?: Yes or No	I Pol C mm
st Repairs: days Res.: Yes or No	mm Ubai. 5 mm
um Sum: % 3 Val.: Yes or No	- 11770 - DIO - 11770
	Survey held at TTIPIE - T Admobile
A / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
ate:Person Contacted: Vehicle: IN /	T. 1
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
MV-53K	
1	T
SUBMIT PRS REPOR	
SUBMIT PRS REPOR	
SUBMIT PRS REPOR	
	Days Of Repair:
ste/Time, File Pass to? : Preli. Report : Final Report	Days Of Repair:
te/Time, File Pass to? : Preli. Report : Final Report	Resurvey No. of Trip: Survey Fee:
te/Time, File Pass to? : Preli. Report : Final Report	Resurvey No. of Trip:  Survey Fee:  Transportation:
te/Time, File Pass to? : Preli. Report : Final Report	Resurvey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$
ste/Time, File Pass to?  : Preli. Report : Final Report ate/Time, File Return to?  Add	Resurvey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ )\$+R\$,\$I  Interview (\$ ) Photos
eport Format:	Resurvey No. of Trip:  Survey Fee:  Transportation:  Stree:  Survey Fee:  Transportation:  Stree:  Transportation:  Stree:  Transportation:  T
ate/Time, File Pass to?  : Preli. Report : Final Report ate/Time, File Return to?	Resurvey No. of Trip:  Survey Fee:  Transportation:  Site Insp (\$ )3+RS,SI  Interview (\$ ) Photos

at (2)Bentol (3)Distorted (4)Cincked (5)Cin (6)Straiched
Scienced (6)Shifted (69)Buckled (19)Busken (11)Heavenry (12)Missing [MOTOR CAR (RB))
con (14)Unconfirmed (15)Not Working

ACTION (A)
(1)Problem (A)
(2)Problem (A)
(3)Problem (A)
(4)Problem (AC)

SLB 2061H

ht Portion C NC Item	COM	XA	oid	MACT	ItiC.	Vehicle No: SLB 20611  Wehicle No: SLB 20611  Wear RIT Door	ON AC	33
was the make the contract of t	4		16.1	1350	993201	Rear RII Door		ļ
16 995327 Frt RII Door	Company at the St	eusse	116.000.0	1351	993284	Rear RII (1)00r Protector		
117 991654 Frt RH Door Protector	1	41000	to same #	1352	995307	Pear RH Door Hinge	day of	
318 991601 Frt RH Door Hinge	esta de Esporto de de	12 200 11 6	Caperonic in a	1353	993228	Rear RII Door Garnish		
319 991685 Frt RH Door Wing Mirror 320 991583 Frt RH Door Garnish	a di agli size Melanir e	44.00	IIIAN F	1354	993278	Rear RH Door Glass Outer Moulding		
321 991639 Frt RH Door Glass Outer Moulding	THE REAL PROPERTY.	pos.	M COURTY	1355	993231	Pear RII Door Glass Inner Moulding		-
322 991588 Frt RH Door Glass Inner Moulding	s is a ferman of	No. of Street,	roccipile is	1356	993229	Rear RH Door Glass		
323 991584 Frt RH Door Glass	is all it also labor to it	V. No. W.		1357	993289	Rear RH Door Glass Regulator		-
324 991595 Frt RH Door Glass Regulator	or checkle supervisorum (h	420.01	Lay respect and	1358	993240	Real RH Door Glass Regulator Motor		
325 991596 Frt RH Door Glass Regulator Motor	# II - NO INCOMPANIES			1359	993294	Rear RH Door Rubber		+-
326 991662 Frt RH Door Rubber	Carlo de diciona di Mili			1360	993276	Rear RH Door Outer Handle		
327 991636 Frt RH Door Outer Handle			consignore to a	1361	993251	Rear RH Door Inner Handle		
328 991607 Frt RH Door Inner Handle		a se returnar d	and Holista or d	1362	993261	Real RH Door Lock		-
329 991625 Frt RH Door Lock w/Key	en casamente er r			1363	993256	Rear R[1 Door Inger Taim Board	-	
130 991624 Fit RII Door Lock		-	to the special control	1364	993218	Rear RII Door Checker Rear RII Door Glass Channel		-
331 991562 Frt RH Door Central Lock				1365	993230	Rear RH Door Glass Triangle Garnish	1	-
332 991675 Frt RH Door Switch				1366	993242	Rear RH Door 1/4 Glass	1	-
33 991617 Frt RH Door lague Thun Board				1367	993285	Rear RH Door 1/4 Glass Rubber	1	1
34 991568 Frt RH Door Checker			سبسا		993288	Rear RH Door 1/4 Glass Pillar	1	
35 991575 Frt RH Door Felt				1369		Rear RH Door Step Garnish	1	-
36 991688 Frt RH Door Wire Harness	-			1370		Rear RH Door Switch	1	
37 991683 Frt RH Door Window Glass Pillar				1371			1	1
38 991640 Frt RH Door Outer Pillar	-					Roof Top Panel	+	1
39 991613 Frt RH Door Inner Pillar				. 1312		Roof Top Moulding	-	+-+
40 991646 Frt RH Door Pillar Inner Garnish				1013		Roof Top Air-bag Roof Top Air-bag Sensor	+	+++
41 990554 Centre Pillar RH				a) 31/4		Roof Top Air-bag Control Unit		+-+
42 990543 Centre Inner Pillar RH				1.316			DEF	1.
43 990518 Centre Pillar Upper Garnish RH				201211		Rear Bumper	- 13	1
44 990565 Centre Pillar Lower Garnish RH				왕(1)(4).7 공(1)(4).8		Rear Bumper Bracket	TRE	1
5 991670 Frt RH Door Step Garnish				3131318		Rear Bumper Side Retainer	TUR	1
6 994058 Rocker Panel RH	-			11/1/2		Rear Bumper Reinforcement		
7 994049 Rocker Panel Inner Panel RH 3 994047 Rocker Panel Garnish RH			-	M150		Rear Bumper Sponge		
3 994047 Rocker Panel Garnish RH 9 994055 Rocker Panel Outer Side Skirt RH				NO.000		Rear Bumper Protector		
991300 Frt Bumper				1116		Rear Bumper Moulding		
991325 Frt Bumper Bracket	-					Rear Bumper Lower Spoiler	_	1
7 001462 Fet Bumper Bracket	<u> </u>			11.60		Kear RH Taillamp		
991462 Frt Bumper Side Retainer 991433 Frt Bumper Reinforcement	-			122		Rear RH Fender		
991468 Fit Bumper Sponge	-					Rear RH Fender Protector Intl	_ CR	1
201400 Fit Bumper Sponge					99024	7 Sticker		
991427 Frt Bumper Protector	-		<b> </b>			Rear RH RIM	CU	TV
991301 Frt Bumper Moulding						Nov. V. Territoria		
991407 Frt Bumper Lower Spoiler					4			
991821 Frt RH Headlamp Assy			1.		'			-
995089 Frt RH Side Lamp					1			
995071 Frt RH Fender		R						
991744 Frt RH Fender Lamp	1							-+
991752 Frt RH Fender Protector	1	-	1-		<del></del>			
State of the color	<del> </del>				+			
			1_					
	-		-					
	_1			1 1			1	