

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD9528U -

Not Authorised
8/1000/-
11/11

Vehicle No.:
 Chassis No.:
 Date of Accident :
 Vehicle Make:
 Vehicle Model:
 Third Party Insurer :

SHD 9528U - ROEL
KL1LA69RJB078045
 06.04.2015
CHEVROLET
CHEVROLET EPICA 2.0
AG

PART		LIST	
1	1 Side Rocker Panel Garnish LH	\$	<i>Sm</i> 236.40 X
2	1 Rear Door LH	\$	<i>R</i> 1,133.00 X
3	1 Rear Door Hinge Upper LH	\$	<i>R</i> 65.00 X
4	1 Rear Door Hinge Lower LH	\$	<i>R</i> 65.00 X
5	1 Rear Door inner lock	\$	<i>R</i> 425.00 X
6	1 Rear Door check / arrestor	\$	<i>Sm</i> 65.00 X
7	1 Rear Door outer weatherstrip moulding	\$	<i>Sm</i> 85.00 X
8	1 Rear Door outer handle	\$	<i>Sm</i> 60.00 X
9	1 Rear Fender LH	\$	<i>R</i> 1,145.00 X
10	1 Rear Fender Inner Cowling LH	\$	<i>Sm</i> 76.60 X
11	1 Rear Bumper	\$	<i>R</i> 1,202.00 X
12	1 Rear Bumper Side Retainer LH	\$	<i>Sm</i> 68.76 X
13	1 Rear Bumper Reflectors LH	\$	<i>Sm</i> 119.74 X
TOTAL		\$	4,746.50
10%		\$	474.65
		\$	4,271.85

Special Nett

1Set	Rear Bumper Parking Sensor	\$	<i>Sm</i> 300.00 X
1 Set	Rear Bumper Fastener Clip	\$	<i>nn</i> 30.00 X
1 Set	Rear Fender Liner Clip	\$	<i>nn</i> 30.00 X
1	Door Sticker "Trans-cab"	\$	<i>nn</i> 80.00 X
1	Door Sticker "6555-3333"	\$	<i>nn</i> 80.00 <i>6555</i>
1set	Side Rocker Panel Garnish Clip LH	\$	<i>nn</i> 60.00 X
1	Rear Tyre LH	\$	<i>Sm</i> 360.00 X
1	Rear Wheel Rim LH	\$	<i>Sm</i> 254.00 X
1	Hub Cup Rim	\$	<i>Sm</i> 35.00 X
1	Rear Fender Advertisement Sticker	\$	<i>nn</i> 250.00 <i>1500</i>
1	Rear Door Advertisement Sticker	\$	<i>nn</i> 250.00 <i>1500</i>

TOTAL \$ 1,729.00

TOTAL PARTS \$ 6,000.85

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHD9528U -

ROEL

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	2,800.00	300
To Rust-Proofing Of The Affected Areas.	\$	220.00	nn X
To transfer of tire, rim and on wheel balancing.	\$	170.00	nn X
Putty and Spray Painting Of The Affected	\$	2,700.00	500
To Check Electrical Lighting Concerned.	\$	170.00	100
To check steering geometry and computer wheel alignment	\$	220.00	nn X
To remove and replace corporate sticker	\$	330.00	600
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	nn X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	nn X

TOTAL \$ 6,950.00

Over All Total \$ 12,950.85

REPAIR DAYS

10 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: