

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

# VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG20005700/UBA3Q2

**Date:** 03/09/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900092561

**Claimant**  
**Vehicle No :** GBC1992R **Insured Vehicle No :** GBJ4793S

Date of Loss: 12/05/2020 Nature of Claim: TP Claim No: 6143178487SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>GBC1992R</b>		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD Turbo (A)	Engine No:	ZD30284686K
Reg. Date:	11/07/2011 (Man. Year: 2011)	Chassis No:	JN1SC2F24Z0850047
Colour:	Silver	Odometer:	153861 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Michelin 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Yokohama 6/6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,861.10	1,874.07	987.03	34.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,200.00	750.00	450.00	37.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,061.10</b>	<b>2,624.07</b>	<b>1,437.03</b>	<b>35.39</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,100.00</b>		
<b>(S\$)</b>	4,061.10	2,100.00	1,961.10	48.29
<b>+ GST 7.00/7.00% (S\$)</b>	284.28	147.00	137.28	48.29
<b>Nett Amount (S\$)</b>	<b>4,345.38</b>	<b>2,247.00</b>	<b>2,098.38</b>	<b>48.29</b>
<b>+ Car Rental (4.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		428.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>2,677.00</b>		
<b>Global Sum Settlement (S\$)</b>		<b>2,600.00</b>		

### INSPECTION

Date of Assignment: 13/05/2020

Date Inspected: 13/05/2020 Inspected At:

Stytech Auto Pte Ltd (HQ)  
2 Kaki Bukit Ave 2 #02-30, Kaki Bukit  
Autohub  
Singapore 417921

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MARCUS CHUA

**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Dented / Bent	1,399.70 F	*1,399.70 FN
2	1		*REAR TAILGATE NISSAN STICKER	Necessary	74.00 F	*74.00 FN
3	1		*70/H STICKER	Necessary	15.00 FS	*10.00 FS
4	1		*WUNDER AUTO STICKER	Not fitted	30.00 FS	* - FS
5	1		*REAR FLOOR END PANEL	Repair	385.20 F	* - FN
6	1		*REAR TAILLAMP (LEFT & RIGHT)	N/S Cracked	497.20 F	*248.60 FN
7	1		*REAR TAILLAMP PANEL(LEFT & RIGHT)	N/S Bent	220.00 F	*110.00 FN
8	1		*REAR NUMBER PLATE	Bent	40.00 FS	*15.00 FS
9	1		*SET REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

<b>Sub Total (\$)</b>	<b>2,861.10</b>	<b>2,057.30</b>
<b>- Nett Item Discount on N Items 0.00/10.00% (\$)</b>	<b>0.00</b>	<b>183.23</b>
<b>Total Parts (\$)</b>	<b>2,861.10</b>	<b>1,874.07</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	CHECK WIRING	New	50.00	20.00
2	ANTI RUST PROOF	New	50.00	30.00
3	PANEL BEATING	New	500.00	300.00
4	PAINT WORK	New	600.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,200.00</b>	<b>750.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >