

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20005702/R1TF3E2

Date: 24/06/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SLJ1011S

Insured Vehicle No : SKN4851E

Date of Loss: 10/05/2020

Nature of Claim:

TP

Claim No: CDMPG20000661

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ1011S**

Make & Model: BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A)

Engine No: 13607829N52B30AF

Reg. Date: 09/12/2011 (Man. Year: 2011)

Chassis No: WBAKB22060C951181

Colour: Black

Odometer: 173386 km

Engine Capacity: 2996 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/50 R18

Rear Tyre Size: 245/50 R18

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,756.50	3,250.50	506.00	13.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	322.50	326.25	-3.75	-1.16
Paintwork Labour	469.48	489.81	-20.33	-4.33
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	4,548.48	4,066.56	481.92	10.60
+ GST 7.00/7.00% (\$\$)	318.39	284.66	33.73	10.59
Nett Amount (\$\$)	4,866.87	4,351.22	515.65	10.60

INSPECTION

Date of Assignment: 13/05/2020 Present Location:

Mova Automotive Pte Ltd (Bukit Merah)

Date Inspected: 18/05/2020 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah)

Blk 1008, #01-04/06/08/94, Bukit Merah

Lane 3

Singapore 159722

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 24 Jun 2020)
Parts:	143	BMW 730LI 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ1011S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/INN U-SONIC SENDER (WCP)	Not Working	200.00 F	*200.00 F
2	1	NA	*R/INN U-SONIC SENDER (WCP)	Not Working	200.00 F	*200.00 F
3	1	NA	*REAR BUMPER ADAPTER (WCP)	Cracked	155.00 F	*155.00 F
4	1	NA	*REAR BUMPER CARRIER (WCP)	Bent	600.00 F	*600.00 F
5	1	NA	*REAR BUMPER COVER (WCP)	Cracked	1,400.00 F	*1,400.00 F
6	1	NA	*REAR BUMPER MNTG KIT (WCP)	Necessary	30.00 F	*30.00 F
7	1	NA	*REAR BUMPER TRIM (WCP)	Repair	280.00 F	*- F
8	1	NA	*REAR CTR FLOOR COVER (WCP)	Cracked	250.00 F	*250.00 F
9	1	NA	*REAR HARNESS (WCP)	Serviceable	180.00 F	*- F
10	1	NA	*RR BUMPER CTR GUIDE (WCP)	Cracked	120.00 F	*120.00 F

F=Franchise part.

Sub Total (S\$)	3,415.00	2,955.00
+ Margin on L,N Items 10.00/10.00% (S\$)	341.50	295.50
Total Parts (S\$)	3,756.50	3,250.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Total Paint Labour	New	324.00	346.50
2	Total Paint Materials	New	145.48	143.31
<u>Labour Items</u>				
3	Total Panel/Mechanical Labour	New	322.50	326.25
Gross Labour Cost (\$\$)			791.98	816.06

Report was unsubmitted during this print-out.

< END OF ESTIMATES >