



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 53 Ubi Ave 1 #01-33 Paya Ubi Industrial Park Singapore 408934

HP: 98888885

Estimation

Date: 12/5/2020

Vehicle: SLC586T

Make / Model: NISSAN QASHQAI

Chassis No: SJNFEAJ11U1637033

No.	Description	Unit	Unit Price	Amount
Parts Replacement:				
1	REAR BUMPER / <i>OD</i>	1	\$ 755.50	\$ 755.50
2	REAR BUMPER REINFORCEMENT ?	1	\$ 674.00	\$ 674.00
3	REAR BUMPER BRACKET LH X	1	\$ 133.80	\$ 133.80
4	REAR BUMPER BRACKET RH X	1	\$ 133.80	\$ 133.80
5	REAR BUMPER SIDE RETAINER LH / <i>BR</i>	1	\$ 47.80	\$ 47.80
6	REAR BUMPER SIDE RETAINER RH / <i>BR</i>	1	\$ 47.80	\$ 47.80
7	REAR END PANEL ?	1	\$ 540.90	\$ 540.90
8	REAR END PANEL TOP GARNISH ?	1	\$ 65.00	\$ 65.00
9	REAR BOOT WEATHER STRIPE / <i>TN</i>	1	\$ 135.90	\$ 135.90
10	REAR TAILLAMP RH X	1	\$ 737.20	\$ 737.20
11	REAR TAILLAMP LH X	1	\$ 737.20	\$ 737.20
12	REAR TAILGATE / <i>OD</i>	1	\$ 3,542.60	\$ 3,542.60
13	REAR TAILGATE LOCK / <i>BT</i>	1	\$ 121.80	\$ 121.80
14	REAR TAILGATE LOCK CATCH X	1	\$ 31.80	\$ 31.80
15	REAR TAILGATE EMBLEM LOGO X	1	\$ 52.50	\$ 52.50
16	REAR TAILGATE EMBLEM QASHQAI / <i>MC</i>	1	\$ 76.40	\$ 76.40
17	REAR TAILGATE INNER TRIM BOARD X	1	\$ 331.10	\$ 331.10
18	REAR TAILGATE LAMP LH X	1	\$ 571.20	\$ 571.20
19	REAR TAILGATE LAMP RH X	1	\$ 571.20	\$ 571.20
				\$ 9,307.50
			Less 10%	\$ 930.75
			Total	\$ 8,376.75
S/Nett items:				
1	REAR REVERSE SENSOR / <i>SL</i>	1 SET	\$ 250.00	\$ 250.00
2	REAR REVERSE CAMERA X	1 SET	\$ 300.00	\$ 300.00
3	REAR BUMPER CLIP / <i>MC</i>	1 SET	\$ 80.00	\$ 80.00
4	REAR END PANEL GARNISH CLIP / <i>MC</i>	1 SET	\$ 60.00	\$ 60.00
5	FLOOR PANEL SEALANT X	1	\$ 50.00	\$ 50.00
6	END PANEL SEALANT ?	1	\$ 50.00	\$ 50.00
7	MISCELLANEOUS X	1	\$ 200.00	\$ 200.00
				\$ 990.00

200
30
20

SLC586T

Labour to:					
1	TO CHECK ELECTRICAL WIRING	1	\$ 80.00	\$ 80.00	30
2	TO REMOVE AND REFIT REVERSE SENSOR/ CAMERA	1	\$ 200.00	\$ 200.00	50
3	REMOVE AND REFIX REAR UPHOLSTERY	1	\$ 200.00	\$ 200.00	X
4	REPAIR AND STRAIGHTEN EXHUAST PIPE	1	\$ 250.00	\$ 250.00	X
5	REMOVE AND TRANSFER ALL REAR TAILGATE FITTING	1	\$ 200.00	\$ 200.00	80
6	REMOVE AND REFIX REAR WINDSCREEN GLASS	1	\$ 150.00	\$ 150.00	120
7	CHECK AND RESET FAULT CODE LIGHT ON	1	\$ 200.00	\$ 200.00	X
8	TO RESPRAY UNDERCOATING	1	\$ 150.00	\$ 150.00	X
9	APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 200.00	\$ 200.00	30
10	SPRAY PAINTING ON AFFECTED AREAS	1	\$ 800.00	\$ 800.00	600
11	PANEL BEATING ON AFFECTED AREAS	1	\$ 1,200.00	\$ 1,200.00	700
				\$ 3,630.00	
		Parts Replacement Amount		\$ 9,366.75	
		Total Amount for Labour		\$ 3,630.00	
		Total Amount		\$ 12,996.75	

Stew (LKK) ML ML
 14/5/20, 4.00pm
 5 days
 L/S
 My AC sy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: