



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 13/05/2020

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB1503U
Case Reference Number	BUS/05/20/1006
Registration Date	20/10/2014
Company Type	SMRT Buses Ltd
Make	MAN
Model	A22
Name of Driver	Tan Boon Keng
Type of Accident	Side Swipe
Accident Date and Time	8/5/2020 5:03 PM
Accident Reported Date and Time	12/5/2020 11:31 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1503U-RIGHT FRONT PORTION SKZ6122A (TP) INSURED WITH
Prepared Date and Time	12/5/2020 1:16 PM
Chassis Number	WMAA22ZZ4E7002265
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$708.00	\$0.00
Total Spare Part Cost	\$1,805.76	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,573.76	\$0.00
Lump Sum Total	\$3,550.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	12/05/2020 1:24 PM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 13/05/2020

User ID : BoonChewTay

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$1,060.00	530.
Total Labour	\$1,060.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$708.00	616.
Total Spray Painting & Panel Beating	\$708.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009985	BODY RH	A01001-CW570	PANEL, SIDE:R4 WITH FRAME, FOR MAN A22 BUS	1.00	\$499.70	100.00	\$0.00	Repair	XK
6010152	Body	F01001-CW266	COVER, HEADLAMP: FRT .RH, FOR MAN A22 BUS	1.00	\$974.70	100.00	\$0.00	Repair	Xh
6010305	VE	81.25101-6540	HEADLAMP, RH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	? X SVC
6010307	VE	81.25320-6112	FLASHER, AUX HEADLAMP, RH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	? X SVC
Total					\$3,982.40		\$2,257.20		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 2 days

L/S.

After paint photo.

Run Pm (21k)

13/05/2020

TP without prejudice.