

EQ - LKK Kenneth



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

GBH 3225 H

Not Authorized

Repairing B4 / After Paint

Parts	(a) Cost / List Price Items	
	Plus/Less	
	Total of Cost / List	
	(b) Nett Price Items	\$ 8,905.50
	Less 10%	\$ 890.55
	Total of Nett Item	\$ 8,014.95
	(c) Special Nett Items	\$ 785.00
Total Parts Cost		\$ 8,799.95
Labour		\$ 4,560.00
Total		\$ 13,359.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 13/5/20 at 11.40am

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 14 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor : PC Date: 13/5/20



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **GBH 3225 H**
Make & Model : **NISSAN NV200**
Chassis No : **VSKYBAM20Z0157695**

Submit By : **JENNY**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Tail door glass RH <i>Shatter</i>	1	\$579.50	N	✓
2	Tail door glass sealant LH & RH <i>me</i>	2	\$100.00	S.N	40511
3	Reverse sensor <i>Shatter</i>	1	\$295.00	S.N	200511
4	Rear bumper <i>Bu</i>	1	\$498.70	N	✓
5	Rear bumper clip <i>me</i>	10	\$50.00	N	✓
6	Rear bumper side retainer LH <i>Sn</i>	1	\$36.30	N	X
7	Rear bumper side retainer RH <i>Dis</i>	1	\$36.30	N	✓
8	Rear bumper bracket LH	1	N/A		
9	Rear bumper bracket RH	1	N/A		
10	Rear bumper reflector RH <i>mit</i>	1	\$58.00	N	✓
11	Tail door LH	1	\$1,281.90	N	?
12	Tail door RH <i>Bu</i>	1	\$980.90	N	✓
13	Tail door Hinge RH - upper <i>Bu</i>	1	\$184.60	N	✓
14	Tail door Hinge RH - Lower <i>Bu</i>	1	\$184.60	N	✓
15	Tail door lock <i>Tu</i>	1	\$261.00	N	✓
16	"6" Pax Sticker <i>me</i>	1	\$20.00	S.N	12511
17	70k/m Sticker <i>me</i>	1	\$20.00	S.N	12511
18	Tail door inner trim RH <i>Bu</i>	1	\$123.40	N	✓
19	Tail door trim clip <i>me</i>	10	\$15.00	N	✓
20	Tail door weatherstrip LH	1	\$96.40	N	?
21	Tail door weatherstrip RH <i>Gu</i>	1	\$96.40	N	✓
22	Tail lamp RH <i>Bu</i>	1	\$236.50	N	✓
23	Tail lamp inner panel RH <i>Bu</i>	1	\$226.40	N	✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Blk 5033 Ang Mo Kio Industrial Park 2 #01-259 Singapore 569536 Tel: 64841221 Fax: 64847829
Company Reg No. 200005485N / GST No. 20-0005485-N

Spare Parts

Vehicle No. : **GBH 3225 H**
Make & Model : **NISSAN NV200**
Chassis No : **VSKYBAM20Z0157695**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	RH Rear fender - Upper <i>Bu</i>	1	\$1,554.60	N	<i>✓</i>
25	RH Rear fender - Lower <i>Bu</i>	1	\$343.60	N	<i>✓</i>
26	RH rear fender centre garnish <i>Dix</i>	1	\$95.40	N	<i>✓</i>
27	RH rear fender inner trim <i>cm</i>	1	\$245.60	N	<i>✓</i>
28	RH sliding door	1	\$1,380.50	N	<i>?</i>
29	RH rear rim <i>P,?</i> <i>nd</i>	1	\$339.90	N	<i>✓</i>
30	RH rear tyre <i>Th</i>	1	\$350.00	S.N	<i>202sn</i>
31					
32					
33					
34					
35					
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **GBH 3225 H**
Make & Model : **NISSAN NV200**

Submit By : **Carmen Lim**
Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR LH, TAIL DOOR RH, RHR FENDER UPPER, RHR FENDER LOWER, RH SLIDING DOOR, TAIL LAMP INNER PANEL RH)	\$1,600.00	1500
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAIL DOOR LH, TAIL DOOR RH, RHR FENDER UPPER, RHR FENDER LOWER, RH SLIDING DOOR, TAIL LAMP INNER PANEL RH)	\$1,600.00	1400
3	To check wiring	\$50.00	20
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$120.00	80
5	To do wheel alignment.	\$120.00	60
6	To remove & refit tail door glass RH	\$120.00	50
7	To tuff coat.	\$250.00	90
8	To do art work. (Tail door LH, RH rear fender, RH sliding door)	\$250.00	?
9	To transfer boot mechanism to new boot	\$150.00	60
10	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Company Reg No. 200005485N / GST No. 20-0005485-N

Vehicle No. : GBH 3225 H
Make & Model : NISSAN NV200

Submit By : Carmen Lim
Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Scanned with CamScanner