

**LOCK PARTS CONTAINING HAZARDOUS
THE REPAIRER OF THE FOLLOWING:**

- No necessary safety precautions required
- No need for hazardous waste disposal necessary
- Parts are not subject to contamination
- Third party liability is not a financial consideration
- No legal notification is required
- Single-party liability must be removed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

ESTIMATE

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate <i>PD</i>	1PC	\$ 1,470.00	\$ 1,470.00
2	Rear tailgate weatherstrip <i>CR4</i>	1PC	\$ 360.00	\$ 360.00
3	Rear tailgate lock assy <i>with outer lamp</i>	1PC	\$ 504.00	\$ 504.00
4	Rear tailgate lock catch <i>?</i>	1PC	\$ 64.80	\$ 64.80
5	Rear tailgate LH damper <i>?</i>	1PC	\$ 352.80	\$ 352.80
6	Rear tailgate RH damper <i>?</i>	1PC	\$ 352.80	\$ 352.80
7	Rear tailgate back door trimboard <i>?</i>	1PC	\$ 580.00	\$ 580.00
8	Rear tray luggage compartment <i>?</i>	1PC	\$ 420.00	\$ 420.00
9	Rear spare tyre compartment box <i>?</i>	1PC	\$ 400.00	\$ 400.00
10	Rear spare tyre panel <i>?</i>	1PC	\$ 1,200.00	\$ 1,200.00
11	Rear tailgate center garnish holder <i>CR4</i>	1PC	\$ 342.00	\$ 342.00
12	Rear tailgate Toyota logo <i>NEC</i>	1PC	\$ 60.00	\$ 60.00
13	Rear licence lamp <i>?</i>	1PC	\$ 120.00	\$ 120.00
14	R/R taillamp <i>?</i>	1PC	\$ 550.00	\$ 550.00
15	R/L taillamp <i>CRU</i>	1PC	\$ 550.00	\$ 550.00
16	R/L tailgate reflector <i>CR4</i>	1PC	\$ 380.00	\$ 380.00
17	R/R tailgate reflector <i>CR4</i>	1PC	\$ 380.00	\$ 380.00
18	Rear end panel <i>PD</i>	1PC	\$ 828.00	\$ 828.00
19	Rear end panel lower <i>?</i>	1PC	\$ 633.60	\$ 633.60
20	Rear end panel top garnish <i>CR4</i>	1PC	\$ 250.00	\$ 250.00
21	Rear bumper cover <i>CRU</i>	1PC	\$ 900.00	\$ 900.00
22	Rear bumper LH side bracket <i>?</i>	1PC	\$ 105.00	\$ 105.00
23	Rear bumper RH side bracket <i>?</i>	1PC	\$ 105.00	\$ 105.00
24	Rear bumper LH bracket <i>?</i>	1PC	\$ 90.00	\$ 90.00
25	Rear bumper RH bracket <i>?</i>	1PC	\$ 90.00	\$ 90.00
26	Rear bumper RH support <i>?</i>	1PC	\$ 88.05	\$ 88.05
27	Rear bumper LH support <i>?</i>	1PC	\$ 88.05	\$ 88.05
28	Rear bumper LH extension side pad <i>X R</i>	1PC	\$ 216.00	\$ 216.00
29	Rear bumper RH extension side pad <i>X R</i>	1PC	\$ 216.00	\$ 216.00
30	Rear bumper center black pad <i>CRU</i>	1PC	\$ 288.00	\$ 288.00
31	Rear bumper RH reflector <i>X Svc</i>	1PC	\$ 133.20	\$ 133.20
32	Rear bumper LH reflector <i>X Svc</i>	1PC	\$ 133.20	\$ 133.20

- 33 Rear bumper tow cover ✓ SCR
34 Keyless smart buzzer antenna ?

1PC	\$	40.00	\$	40.00
1PC	\$	120.00	\$	120.00
LIST TOTAL S\$:				\$ 12,410.50
25.00% DISCOUNT S\$:				\$ 3,102.63
				\$ 9,307.88

SPECIAL NETT

- 1 Bumper clips ✓ Nec
2 Reverse sensor ✓ Nec
3 Windscreen sealant ✓ Nec
4 Rear number plate ✓ Nec

1 SET	\$	80.00	30
1 SET	\$	260.00	200
1PC	\$	100.00	40
1PC	\$	60.00	35
Special Nett Total S\$:	\$	500.00	

LABOUR CHARGES

- | | | |
|---|---|-----------------|
| 1 | To remove and install rear tailgate glass | \$ 120.00 ✓ |
| 2 | Transfer tailgate mechanism | \$ 100.00 60 |
| | To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts. Also include straightening of both rear chassis members and floor panel. | |
| 3 | | \$ 1,200.00 800 |
| | To respray rear tailgate, rear end panel, spare tyre panel, rear bumper, roof top and both rear fenders | |
| 4 | | \$ 1,200.00 800 |
| | To remove upholstery, seats out to facilitate repairs and replacement of damaged parts | |
| 5 | | \$ 180.00 100 |
| | To conduct a standard of operating procedures post repairs diagnostic scan test as a requirements upon completion of collision repairs | |
| 6 | | \$ 300.00 X |

LABOUR TOTAL S\$:	\$ 3,100.00
TOTAL S\$:	\$ 12,907.88
7% GST	\$ 903.55
GRAND TOTAL S\$:	<u>\$ 13,811.43</u>

Repair day - 5 days

L/S.

After paint photo

Sun Pin (LH)

13/05/2020

TP without prejudice.