

Like Auto Components, Underwriting
the Repayment of the Subsidy:

- To determine nature of company business
- To assess management quality to pay money
- Plans given are subject to examination
- Third party survey is to be through financial bases
- No. Bargain mortgage for 15 years
- Single mortgage term must be approved and is subject to final approval from Insurance Company

Acknowledged by Repayer
 Signature:
 Date:

ESTIMATE

VEHICLE NO. SLE7243B
CHASSIS NO : NSP1707026602
MAKE / MODEL : Toyota Sienta 1.5X Auto
DATE OF ACCIDENT : 04/05/2020
YOUR INSURED VEHICLE NUMBER :SKE8358J
MILEAGE : 219916km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate / PD	1PC	\$ 1,470.00	\$ 1,470.00 1,250
2	Rear tailgate weatherstrip / CR4	1PC	\$ 360.00	\$ 360.00 ✓
3	Rear tailgate lock assy with counter lamp / sum	1PC	\$ 504.00	\$ 504.00 372
4	Rear tailgate lock catch ? XSVC	1PC	\$ 64.80	\$ 64.80 X
5	Rear tailgate LH damper ? XSVC	1PC	\$ 352.80	\$ 352.80 X
6	Rear tailgate RH damper ? XSVC	1PC	\$ 352.80	\$ 352.80 X
7	Rear tailgate back door trimboard ? XSVC	1PC	\$ 580.00	\$ 580.00 X
8	Rear tray luggage compartment ? / CR4	1PC	\$ 420.00	\$ 420.00 380
9	Rear spare tyre compartment box ? XSVC	1PC	\$ 400.00	\$ 400.00 X
10	Rear spare tyre panel ? / PD	1PC	\$ 1,200.00	\$ 1,200.00 899.10
11	Rear tailgate center garnish holder / CRA	1PC	\$ 342.00	\$ 342.00 ✓
12	Rear tailgate Toyota logo / NRC	1PC	\$ 60.00	\$ 60.00 ✓
13	Rear licence lamp ? XSVC	1PC	\$ 120.00	\$ 120.00 X
14	R/R taillamp ? / CRA	1PC	\$ 550.00	\$ 550.00 ✓
15	R/L taillamp / CR4	1PC	\$ 550.00	\$ 550.00 ✓
16	R/L tailgate reflector / CR4	1PC	\$ 380.00	\$ 380.00 ✓
17	R/R tailgate reflector / CR4	1PC	\$ 380.00	\$ 380.00 ✓
18	Rear end panel / PD	1PC	\$ 828.00	\$ 828.00 600
19	Rear end panel lower ? XSVC	1PC	\$ 633.60	\$ 633.60 X
20	Rear end panel top garnish / CR4	1PC	\$ 250.00	\$ 250.00 180
21	Rear bumper cover / CR4	1PC	\$ 900.00	\$ 900.00 640
22	Rear bumper LH side bracket ? / BR	1PC	\$ 105.00	\$ 105.00 ✓
23	Rear bumper RH side bracket ? XSVC	1PC	\$ 105.00	\$ 105.00 X
24	Rear bumper LH bracket ? / BR	1PC	\$ 90.00	\$ 90.00 ✓
25	Rear bumper RH bracket ? XSVC	1PC	\$ 90.00	\$ 90.00 X
26	Rear bumper LH support ? XSVC	1PC	\$ 88.05	\$ 88.05 X
27	Rear bumper LH support ? XSVC	1PC	\$ 88.05	\$ 88.05 X
28	Rear bumper LH extension side pad X R	1PC	\$ 216.00	\$ 216.00 X
29	Rear bumper RH extension side pad X R	1PC	\$ 216.00	\$ 216.00 X
30	Rear bumper center black pad / CR4	1PC	\$ 288.00	\$ 288.00 ✓
31	Rear bumper RH reflector X SVC	1PC	\$ 133.20	\$ 133.20 X
32	Rear bumper LH reflector X SVC	1PC	\$ 133.20	\$ 133.20 X

- 33 Rear bumper tow cover ✓ SCR
34 Keyless smart buzzer antenna ? XSVC

1PC	\$	40.00	\$	40.00	✓
1PC	\$	120.00	\$	120.00	X
LIST TOTAL S\$:					\$ 12,410.50
25.00% DISCOUNT S\$:					\$ 3,102.63
					\$ 9,307.88
					7,466.10
					-25%
					5,599.58

SPECIAL NETT

- 1 Bumper clips ✓ Nec
2 Reverse sensor ✓ Nec
3 Windscreen sealant ✓ Nec
4 Rear number plate ✓ Nec

1 SET	\$	80.00	30
1 SET	\$	260.00	200
1PC	\$	100.00	40
1PC	\$	60.00	35
Special Nett Total S\$:		\$	500.00
			305

LABOUR CHARGES

- | | | |
|---|---|----------------------------------|
| 1 | To remove and install rear tailgate glass | \$ 120.00 ✓ |
| 2 | Transfer tailgate mechanism | \$ 100.00 60 |
| | To labour charge for removing rear tailgate, rear bumper, end panel and spare tyre panel out to facilitate repairs and replacement of damaged parts. Also include straightening of both rear chassis members and floor panel. | |
| 3 | | \$ 1,200.00 800 1,000 |
| | To respray rear tailgate, rear end panel, spare tyre panel, rear bumper, roof top and both rear fenders | |
| 4 | | \$ 1,200.00 800 950 |
| | To remove upholstery, seats out to facilitate repairs and replacement of damaged parts | |
| 5 | | \$ 180.00 160 |
| | To conduct a standard of operating procedures post repairs diagnostic scan test as a requirements upon completion of collision repairs | |
| 6 | | \$ 300.00 X |

LABOUR TOTAL S\$:	\$ 3,100.00	2,230
TOTAL S\$:	\$ 12,907.88	
7% GST	\$ 903.55	
GRAND TOTAL S\$:	<u>\$ 13,811.43</u>	

Repair day - ~~15~~ 8 days

L/S.

After paint photo

Sun Pin (LH)

13/05/2020

TP without prejudice.

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date:25/07/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE (Parts Supplementary)

VEHICLE NO. SLE7243B

CHASSIS NO : NSP1707026602

MAKE / MODEL : Toyota Sienta 1.5X Auto

DATE OF ACCIDENT : 04/05/2020

YOUR INSURED VEHICLE NUMBER :SKE8358J

MILEAGE : 229212 km

<u>PARTS DESCRIPTION</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear tailgate handgrip /CR4	1PC	\$ 60.00	\$ 60.00 45
2	Rear wiper cover /CRA	1PC	\$ 25.00	\$ 25.00 /
3	R/L fender inner trim board /CR4	1PC	\$ 780.00	\$ 780.00 650
4	R/R fender inner trim board /CR4	1PC	\$ 780.00	\$ 780.00 650
5	R/L fender outer garnish ✓ CRU	1PC	\$ 555.00	\$ 555.00 322
LIST TOTAL S\$:				\$ 2,200.00 1,692
25.00% DISCOUNT S\$:				\$ 550.00 -25%
				\$ 1,650.00 1,269
7% GST				\$ 115.50
GRAND TOTAL S\$:				\$ 1,765.50

5,594.58
305
2,230
1,269
9,403.58
- 20%
7,522.86
L/S
\$7,500
8days