


ANNAETH

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s Estem
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____



(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 02 days Res.: Yes or No
 Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SL5 419J Yr Regn: 09.17
 Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toy Pro c.c. 1798
 Colour: M. Silver A/C: Insured / Std / Nil / NA
 Sp. Reading: 273857 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: JTDKB3FU103569498
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modl: Nil / S/Rlm / STD A/Rlm or
 Tyre Size: F: 195/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or

Front	Rear
R/Bal. <u>8</u> mm	R/Bal. <u>8</u> mm
L/Bal. <u>8</u> mm	L/Bal. <u>8</u> mm
D.O.A. <u>10/5/20</u>	D.O.I. <u>18/5/2020</u>

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>26/5</u>	<u>1251.60 Confirm (Red 2678.51,68%)</u>

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: 2

☐ : Final Report

Resurvey No. of Trlp: 1

Date/Time, File Return to?

26/5/20-Typist

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ - RS. \$


Fees

Others

Report Format: TP

Lump Sum / I.B.I: (\$ 1251.60)

TOTAL



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.

Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

are Parts

icle No. :

SLS 419 J

e & Model :

TOYOTA PRIUS

ssis No :

JTDMB3FU103569498

Submit By :

Serence chee

Year Manufacture :

2017

Engine No. :

Cost / List

P.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>nd</i>	1	\$45.00	S.N	✓
2	Front number plate garnish <i>cm</i>	1	\$129.00		✓
3	Front bumper <i>Avic/cm</i>	1	\$450.80		✓
4	Front bumper clip <i>nc</i>	10	\$40.00		✓
5	Front bumper reinforcement - upper <i>R</i>	1	\$711.50		X
6	Front bumper reinforcement - lower <i>R</i>	1	\$245.30		X
	Front bumper side retainer RH <i>Sn</i>	1	\$107.20		X
	Front bumper side retainer LH <i>Sn</i>	1	\$107.20		X
	Front bumper upper grille <i>Dr</i>	1	\$321.90		✓
	Front bumper lower grille <i>Sn</i>	1	\$148.60		X
	Front bumper emblem <i>nc</i>	1	\$87.10		✓
	Front bumper tow cover RH <i>R</i>	1	\$25.70		X
	Front bumper tow cover LH <i>Sn</i>	1	\$25.70		X
	Front bumper sponge - upper <i>Sn</i>	1	\$89.81		X
	Front bumper sponge - lower <i>Sn</i>	1	\$135.70		X
	Fog lamp RH <i>Sn</i>	1	\$910.70		X
	Engine under cover <i>Sn</i>	1	\$198.30		X
	Engine under cover clip <i>nn</i>	10	\$35.00		X
	RH front fender undershield <i>Sn</i>	1	\$185.64		X
	RH front fender undershield clip <i>nn</i>	10	\$25.00		X

any of the quoted parts are recommended to be repaired, then an additional labour charge

charged accordingly under supplementary.

Submit By : Serence chee
Year of Manufacture : 2017