

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHD 9799D

AAD2005-027

Not Authorized
44p \$ 220/h

Vehicle No.: 13 MAY 2020

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHD 9799D

VF1ABL15AUC277293

RENAULT

LATITUDE

12.5.2020

LONPAC

14/4/2014

PART		LIST	
1	BUMPER COVER REAR	\$ <i>n</i> (<i>Pen</i>)	561.70 <i>x</i>
1	BUMPER LOWER REAR	\$ <i>sn</i>	411.90
1	BUMPER BRACKET CTR REAR	\$ <i>sn</i>	98.10
1	BUMPER BRACKET SIDE RH REAR	\$ <i>sn</i>	82.10
1	BUMPER RETAINER RH REAR	\$ <i>sn</i>	59.80
1	BUMPER REFLECTOR RH	\$ <i>sn</i>	16.60
1	BUMPER BRACKET SIDE LH REAR	\$ <i>sn</i>	80.80
1	BUMPER RETAINER LH REAR	\$ <i>sn</i>	54.20
1	BUMPER REFLECTOR LH	\$ <i>sn</i>	16.60
1	BUMPER BEAM REAR	\$ <i>n</i>	547.80
1	BUMPER BEAM BRACKET LH REAR	\$ <i>n</i>	114.50
1	BUMPER BEAM BRACKET RH REAR	\$ <i>n</i>	100.90
1	OUTER PANEL REAR (End Panel)	\$ <i>n</i>	745.80
1	OUTER PANEL REAR (End Panel) TRIM	\$ <i>sn</i>	404.56
1	TAILLAMP RH	\$ <i>sn</i>	313.10
1	TAILLAMP PANEL RH	\$ <i>n</i>	401.40
1	TAILLAMP LH	\$ <i>sn</i>	401.40
1	TAILLAMP PANEL LH	\$ <i>n</i>	401.40
1	BOOT REAR	\$ <i>n</i>	1,677.20
1	BOOT FINISHER	\$ <i>sn</i>	344.70
1	BOOT WHEATERSTRIP	\$ <i>sn</i>	178.20
1	BOOT REFLECTOR LAMP LH	\$ <i>sn</i>	277.70
1	BOOT REFLECTOR LAMP RH	\$ <i>sn</i>	277.70
1	BOOT BADGE 'RENAULT'	\$ <i>nn</i>	82.40
1	BOOT BADGE	\$ <i>nn</i>	95.80
1	BOOT STRUT LH	\$ <i>sn</i>	145.10

Trans-cab Auto Services Pte Ltd

AAD2005-027

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9799D

1	BOOT STRUT RH	\$	145.10	} <i>Sub X</i>
1	BOOT HINGE LH	\$	254.20	
1	BOOT HINGE RH	\$	253.80	
1	BOOT INNER TRIM BOARD	\$	611.00	
1	BOOT LOCK	\$	246.60	
1	EXHAUST CAP REAR	\$	125.40	
1	SPARE TYRE BOARD	\$	680.90	
TOTAL		\$	10,208.46	
10%		\$	1,020.85	
		\$	9,187.61	

Special Nett

1SET	PARKING AID	\$	<i>Sub</i> 700.00	} <i>X</i>
1SET	REAR BUMPER CLIP	\$	<i>nn</i> 68.00	
1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i> 35.00	
1SET	BUMPER BRACKET SIDE CLIP RH RR	\$	<i>nn</i> 25.00	
1SET	BUMPER RETAINER RH CLIP RR	\$	<i>nn</i> 35.00	
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	<i>nn</i> 25.00	
1SET	BUMPER RETAINER CLIP LH RR	\$	<i>nn</i> 35.00	
1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i> 30.00	
1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i> 68.00	
1	BOOT STICKER "Trans-cab"	\$	<i>nn</i> 35.00	
1	BOOT STICKER "6555-3333"	\$	<i>nn</i> 35.00	
1	BOOT INNER TRIM CLIP	\$	<i>nn</i> 45.00	
1SET	BOOT FINISHER CLIP	\$	<i>nn</i> 35.00	
1	TAILLAMP CLIP LH	\$	<i>nn</i> 25.00	
1	TAILLAMP CLIP RH	\$	<i>nn</i> 25.00	
1	Rear Bumper Protector	\$	<i>nn</i> 120.00	
1	REAR LICENCE PLATE WITH HOLDER	\$	<i>Sub</i> 100.00	
TOTAL		\$	1,441.00	

TOTAL PARTS \$ 10,628.61**LABOUR**

Trans-cab Auto Services Pte Ltd

AAD2005-027

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9799D

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	4 170.00	X
To Check Electrical Lighting Concerned.	\$	4 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	4 380.00	X
To check steering geometry and computer wheel alignment	\$	4 220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	4 380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	4 170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4 6,000.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	4 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
To reinstall rear bumper parking sensor.	\$	4 170.00	X
Putty and spray painting of the affected portion.	\$	6,000.00	2201
TOTAL	\$	14,170.00	

Over All Total \$ 24,798.61

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LUMP SUM (REPAIR DAY)**20 DAYS**

1 day