



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDW412B

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Rasul

Finalization

Vehicle & Document Information

WIP No 42772
Reg No/Reg Date SDW412B / 10/03/2017
Date In/Mileage 22/06/2020 / 34159
Chassis No WDD2050402R246605
Engine No 27491030834138
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 029 992 Selenite Gr/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	28/07/2020/ 16:36	AQ	305 / Alan Quek Ai Lun
Description of Goods / Services				
Qty	Unit Price	Disc%	Amount	

M BPNSUN

POLICY NO/ACC DATE : 2100503444 // 12-05-2020
DRIVE IN: 13-05-2020 // TP CAR NO: SJL8285K (CHINA TAIPING INS)
DATE IN/DATE SURVEY: 22-06-2020 // LKK RASUL
BY/AUTHORIZED ON : TAN KAH LEONG // 22-06-2020

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

CHECK HEADLAMP WITH FOCUS ADJUSTMENT.NETT

A BPILAB

REMOVE & REPLACE FRONT BUMPER & REMOVE FRONT SUPPORT
ASSY COMPONENTS & REFINISH.

A BPIRES

RESPRAY FRONT BUMPER

X RH/F HEADLAMP

X FRT BUMPER

X RH/F BUMPER BRACKET

X RH/F PARKING SENSOR SEAL

X RH/F BUMPER BRACKET

0.10 380.00

120.00

960.00

600.00

1.00 3280.44 00.00 3280.44

1.00 1580.69 00.00 1580.69

1.00 12.94 00.00 12.94

1.00 6.35 00.00 6.35

1.00 73.70 00.00 73.70

3 Days
ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 7,014.12
7% GST on 7014.12 490.99

Authorized signatory and company stamp

Total Payable 7,505.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SDW412B

SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 42772
Reg No/Reg Date SDW412B / 10/03/2017
Date In/Mileage 22/06/2020 / 34159
Chassis No WDD2050402R246605
Engine No 27491030834138
Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim 029 992 Selenite Gr/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator	
WC000668	Credit	28/07/2020/ 16:36	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE : 2100503444 // 12-05-2020
DRIVE IN: 13-05-2020 // TP CAR NO: SJL8285K (CHINA TAIPING INS)
DATE IN/DATE SURVEY: 22-06-2020 // LKK RASUL
BY/AUTHORIZED ON : TAN KAH LEONG // 22-06-2020
X RH/F BUMPER BRACKET

1.00 73.70 00.00 73.70

ESTIMATE

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on 73.70 5.16
Total Payable 78.86

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

