

# GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

CARRO LEASING PTE LTD  
8 KAKI BUKIT AVE 4  
# 05-25 PREMIER @ KB  
Singapore 415875

12<sup>th</sup> MAY 2020

TP China.  
Ashes.

MHF BT9F3206022802

Accident date: 12<sup>th</sup> MAY 2020  
Estimated repair cost for vehicle no: SKQ7764M TOYOTA VIOS (E) '2014

S/n	Qty	Items	U/price	Amount	
1	1	Rear Tail Lamp-RH <i>ut</i>		\$333.70	✓
2	4	Rear Tail Lamp Clips <i>new</i>	\$6.50	<del>\$26.00</del>	10
3	1	Rear Tail Lamp Panel <i>new</i>		\$281.10	X
4	1	Rear Bumper <i>torn</i>		\$581.75	✓
5	8	Rear Bumper Clips <i>new</i>	\$6.50	<del>\$52.00</del>	30
6	1	Rear Bumper Reverse Sensor <i>new</i>		\$350.00	X
7	1	Rear Bumper Bracket <i>new</i>		\$131.70	58
8	1	Rear Bumper Side Reflector -RH <i>new</i>		\$83.10	X
9	1	Rear Fender- RH <i>new</i>		\$972.40	X
10	1	Rear Fender Inner Trim Board-RH <i>new</i>		\$325.10	X
11	10	Rear Fender Inner Trim Board Clips <i>new</i>	\$6.50	\$65.00	X
12	1	rear fender mud -shiled <i>new</i>		\$112.10	X
13	2	rear fender mud shiled clips <i>new</i>	\$12.90	\$25.80	X
14	1	Rear door <i>new</i>		\$1,020.00	X
15	1	rear door handle <i>new</i>		\$155.20	X
16	1	Rear tire-RH <i>ut</i>		<del>\$350.00</del>	150 (SN).
17	1	Rear axle assy <i>Best</i>		<del>\$2,350.00</del>	1955
18	1	Rear rim-RH <i>ut</i>		\$400.00	✓
19	1	Rear Axle bearing-RH <i>new</i>		\$358.00	✓

Subtotal :- \$7,972.95

## Labour charges

To remove & refit cushion

3726.45 S.N: 150 \$150.00 50

2794.83

\$120.00 50

To remove & refit reverse sensor

\$380.00 280

to remove & refix rear undercarriage with axle assy

\$80.00 30

To check wiring

\$120.00 80

WHeel alignment ( computer

1550 \$120.00 60

Tuff kote

\$800.00 400

Panel beating

\$800.00 600

Spray painting

Subtotal :-

\$2,570.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total :-

\$10,542.95

total: 4494.83

W/S: 3.6K 05 Dup.