

GREEN FOREST AUTOMOBILE PTE LTD

8 Kaki Bukit Avenue 4, #05-25 Premier @ Kaki Bukit Singapore 415875

12th MAY 2020

CARRO LEASING PTE LTD
8 KAKI BUKIT AVE 4
05-25 PREMIER @ KB
Singapore 415875

Accident date: 12st MAY 2020
Estimated repair cost for vehicle no: SKQ7764M TOYOTA VIOS (E) '2014

S/n	Qty	Items	U/price	Amount
				\$333.70
1	1	Rear Tail Lamp-RH		\$26.00
2	4	Rear Tail Lamp Clips	\$6.50	\$281.10
3	1	Rear Tail Lamp Panel		\$581.75
4	1	Rear Bumper		\$52.00
5	8	Rear Bumper Clips	\$6.50	\$350.00
6	1	Rear Bumper Reverse Sensor		\$131.70
7	1	Rear Bumper Bracket		\$83.10
8	1	Rear Bumper Side Reflector -RH		\$972.40
9	1	Rear Fender- RH		\$325.10
10	1	Rear Fender Inner Trim Board-RH		\$65.00
11	10	Rear Fender Inner Trim Board Clips	\$6.50	\$112.10
12	1	rear fender mud -shiled		\$25.80
13	2	rear fender mud shiled clips	\$12.90	\$1,020.00
14	1	Rear door		\$155.20
15	1	rear door handle		\$350.00
16	1	Rear tire-RH		\$2,350.00
17	1	Rear axle assy		\$400.00
18	1	Rear rim-RH		\$358.00
19	1	Rear Axle bearing-RH		
Subtotal :-				\$7,972.95
Labour charges				\$150.00
To remove & refit cushion				
To remove & refit reverse sensor				\$120.00
to remove & refix rear undercarriage with axle assy				\$380.00
To check wiring				\$80.00
Wheel alignment (computer)				\$120.00
Tuff kote				\$120.00
Panel beating				\$800.00
Spray painting				\$800.00
Subtotal :-				\$2,570.00
Total:-				\$10,542.95