

SIN FATT DIESEL MOTOR

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

HP: 92712214

Business Reg. No : 377435/00K

14th MAY 2020

TEO HOCK BENG
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

Accident date: 12th MAY 2020

Estimated repair costs for vehicle no:SLL7137M Toyota Harrier 2.0 / 2017

S/n	Qty	Items	U/price	Amount
				\$2,228.80
1	1	Rear Boot Lid		\$408.10
2	1	Rear Boot Lid Inner Lock		\$638.20
3	1	boot lid inner trim board		\$186.20
4	1	boot lid lock cover		\$325.10
5	1	boot lid centre moulding		\$299.10
6	1	Rear boot lid inner rubber		\$50.00
7	1	Rear Boot Lid Number Plate		\$166.20
8	2	Rear Boot Lid Number Plate Lamp	\$83.10	\$80.00
9	1	Rear Boot Lid toyota logo		\$65.00
10	1	harrier logo		\$850.40
11	2	boot lid side reflector	\$425.20	\$1,376.40
12	2	Rear tail lamp	\$688.20	\$51.60
13	4	Rear tail lamp clips	\$12.90	\$310.40
14	2	rear bumper side retainer	\$155.20	\$795.90
15	1	Rear bumper reinforcement		\$224.20
16	2	Rear bumper side bracket	\$112.10	\$350.00
17	1	Rear bumper reverse sensor		\$269.90
18	1	Rear bumper inner sponge		\$1,525.50
19	1	Rear bumper		\$535.20
20	1	rear bumper lower cover		\$136.40
21	2	Rear bumper side reflector	\$68.20	\$628.00
22	1	Rear end panel		\$285.10
23	1	end panel top garnish		\$265.10
24	1	end panel lower garnish		\$100.00
25	1	end panel sealant		\$1,655.20
26	1	Rear spare tyre panel		\$250.00
27	1	rear floor panel top sealant		\$855.20
28	1	Rear floor panel top cover		
Subtotal :-				\$14,911.20

<u>Labour charges</u>	\$150.00
Remove and refix rear windscreen	\$50.00
Gum	\$80.00
To Check Wiring System	\$120.00
TO Remove & Refix rear cushion	\$120.00
remove and refix rear reverse sensor	\$150.00
Tuff kote	\$1,400.00
Panel beating	\$1,200.00
Spray painting charges	\$3,270.00
	<u>\$3,270.00</u>
	<u>\$18,181.20</u>
Total:-	