

SIN FATT DIESEL MOTOR

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

HP: 92712214

Business Reg. No : 377435/00K

TEO HOCK BENG
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

TPALG
Cecilia

14th MAY 2020

ZSU 600087101

Accident date 12th MAY 2020
Estimated repair costs for vehicle no SLL7137M Toyota Harrier 2.0 / 2017

Sin	Qty	Items	U/price	Amount	
				\$2,228.80	1712
1	1	Rear Boot Lid		\$408.10	
2	1	Rear Boot Lid Inner Lock		\$638.20	460
3	1	boot lid inner trim board		\$186.20	25
4	1	boot lid lock cover		\$325.10	
5		boot lid centre moulding		\$299.10	
6		Rear boot lid inner rubber		\$50.00	
7	1	Rear Boot Lid Number Plate	\$83.10	\$166.20	
8	2	Rear Boot Lid Number Plate Lamp		\$80.00	
9	1	Rear Boot Lid toyota logo		\$65.00	
10	1	harrier logo	\$425.20	\$850.40	425.20
11	2	boot lid side reflector	\$688.20	\$1,376.40	
12	2	Rear tail lamp	\$12.90	\$51.60	
13	4	Rear tail lamp clips	\$155.20	\$310.40	
14	2	rear bumper side retainer		\$795.90	
15	1	Rear bumper reinforcement	\$112.10	\$224.20	
16	2	Rear bumper side bracket		\$350.00	200 (sw)
17	1	Rear bumper reverse sensor		\$269.90	137
18	1	Rear bumper inner sponge		\$1,525.30	1343
19		Rear bumper		\$535.20	
20	1	rear bumper lower cover	\$68.20	\$136.40	
21	2	Rear bumper side reflector		\$628.00	
22	1	Rear end panel		\$285.10	
23	1	end panel top garnish		\$265.10	
24	1	end panel lower garnish		\$100.00	60 (sw)
25	1	end panel sealant		\$1,655.20	
26	1	Rear spare tyre panel		\$250.00	
27	1	rear floor panel top sealant		\$855.20	509
28	1	Rear floor panel top cover		502	
		Subtotal :-		\$14,911.20	

- Spare Tyre Lock Screw. Best 52 ✓
- Rear End Panel Antenna subd 158 ✓
- Spare Tyre Panel Side Garnish LH. subd 186 ✓
- Spare Tyre Panel Side Garnish RH. 209 ✓
- Spare Tyre Panel Tray subd 445 ✓
- Spare Tyre Panel Sponge Side subd 165 ✓
- Spare Tyre Panel Sponge Centre subd 205 ✓

2434
670050

SN. 260

Labour charges

Remove and refix rear windscreen

Gum

To Check Wiring System

TO Remove & Refix rear cushion

remove and refix rear reverse sensor

Tuff kote

Panel beating

Spray painting charges

~~\$150.00~~ 120

~~\$50.00~~ ✓

~~\$80.00~~ 30

~~\$120.00~~ 80

~~\$120.00~~ 60

~~\$150.00~~ 80

900.00 ~~\$1,400.00~~ 1000

800.00 ~~\$1,200.00~~ 1000

\$3,270.00

\$18,181.20

Total:-

total 9380.50

A/S: 7-5K.

07 Days.

7-5K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: