

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD20005738/ABA3Q2

Date: 29/09/2020

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00016556

Claimant
Vehicle No : SGH8042B **Insured Vehicle No :** SKC3389M

Date of Loss: 05/05/2020 Nature of Claim: TP Claim No: 1202000017349

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGH8042B		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Engine No:	3ZZ4578106
Reg. Date:	23/06/2006 (Man. Year: 2006)	Chassis No:	MR053ZEC107122757
Colour:	Black	Odometer:	328089 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R15	Rear Tyre Size:	195/60 R15
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,697.50	2,233.30	3,464.20	60.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,600.00	1,060.00	1,540.00	59.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,297.50	3,293.30	5,004.20	60.31
Approved Total (Overridden) (S\$)		2,600.00		
Nett Amount (S\$)	8,297.50	2,600.00	5,697.50	68.67
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		3,007.49		
Global Sum Settlement (S\$)		2,900.00		

INSPECTION

Date of Assignment: 14/05/2020

Date Inspected: 15/05/2020 Inspected At:

Hua Meng Spray Painting Workshop
(HQ)

No 1 Kaki Bukit Avenue 6, #01-61

Autobay@Kaki Bukit

Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 29 Sep 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH8042B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	530.10 FL	*461.00 FL
2	1		*FRONT BUMPER SIDE HOLDER	N/S Necessary	383.80 FL	*25.00 FL
3	1		*FRONT BUMPER LH SIDE FOG LAMP COVER	Not Necessary	188.20 FL	*- FL
4	1		*SET FRONT BUMPER CLIPS	Necessary	70.00 FL	*30.00 FL
5	1		*FRONT LH HEADLAMP	Cut	617.80 FL	*445.00 FL
6	1		*FRONT LH FENDER	Dented	639.20 FL	*456.20 FL
7	1		*FRONT LH FENDER SIGNAL LAMP	Not Necessary	25.00 FL	*- FL
8	1		*FRONT LH FENDER INNER SHIELD	Deformed	310.10 FL	*131.40 FL
9	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	70.00 FL	*30.00 FL
10	1		*FRONT LH SHOCK ABSORBER	Not Necessary	640.10 FL	*- FL
11	1		*FRONT LH LOWER ARM	Bent	412.20 FL	*275.10 FL
12	1		*FRONT LH KNUCKLE ARM	Damaged	636.40 FL	*380.10 FL
13	1		*FRONT LH KNUCKLE ARM BEARING	Necessary	210.60 FL	*210.60 FL
14	1		*FRONT LH DRIVE SHAFT	Not Necessary	1,796.50 FL	*- FL
15	1		*FRONT LH WHEEL RIM	Cut	800.00 FS	*400.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,330.00	2,844.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,632.50	611.10
Total Parts (\$\$)	5,697.50	2,233.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	REMOVE & REINSTALL FRONT SUSPENSION	New	400.00	180.00
3	REMOVE ,REPLACE & REPAIR CONSISTEN TO THE ACCIDENT	New	1,100.00	400.00
4	RESPRAY PAINTING	New	1,000.00	400.00
Gross Labour Cost (\$\$)			2,600.00	1,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >