

Vehicle no. : SFX 8336G
 Model : TOYOTA CH-R
 Chassis No: NGX50-2008645
 Estimate - Parts(s)

S/N	Qty	Descriptions	Amount
LIST ITEMS:-			\$
1	1 pc	front bonnet X R	650
2	1 pc	bonnet inner lock X NN	105
3	1pcs	bonnet hinges X NN	80
4	1 pc	front bumper ✓ DD	510
5	1pcs	front bumper rh retainer ✓ BR	90
6	1 set	bumper fastener ✓ NEC	22
7	1 pc	front bumper reinforcement X NN	310
8	1 pc	front bumper upper sponge X NN	98
9	1pcs	front bumper lower sponge X NN	95
10	1pcs	front bumper lower garnish ✓ CUT	345
11	1pcs	front bumper center grille garnish X NN	115
13	1pcs	front grille base ✓ BR	155
14	1pcs	front grille logo emblem X NN	780
15	1pcs	front rh fender ✓ DD	550
16	1pcs	front rh fender side panel protector ✓ CRU	180
17	1pcs	front rh fender inner sheild ✓ TN	185
18	1set	front rh fender inner sheild clips ✓ NEC	25
19	1 pc	front rh wheel arch garnish ✓ CRU	195
20	1 pc	front rh headlamp assy ✓ BR	1255
21	1pc	front rh door X R	915
22	1pcs	front rh door weatherstrip X R	205
23	1pcs	front rh door moudling X NN	230
24	1 pc	front rh door power window motor X NN	390
25	1 pc	front rh shock absorber ✓ BT	350
26	1 pc	front rh wheel bearing ✓ NEC	335
27	1 pc	front rh knuckle arm ✓ BT	365
28	1 pc	front rh lower arm X NN	315
29	1 pc	radiator assy X NN	1155
30	1 pc	A/C condensor X NN	1100
32	1pcs	top support panel X R	245
33	1pcs	rh support panel ✓ BT	125
34	1pcs	lower support panel X NN	365
35	1pcs	support panel top garnish X NN	160
35	1pcs	front rh fog lamp cover ✓ CRU	86
36	1 pc	washer tank ✓ CRU	140
37	1pcs	front engine lower cover garnish ✓ TN	155

P - 5068
-25%
3801

less 25%

12381
3095.25
9285.75

Special Nett

1 1 pc front orignal rim ✓ CUT

550 ✓

N - 550

Vehicle no. : SFX 8336G
 Model : TOYOTA CH-R
 Chassis No: NGX50-2008645

Estimate - Labour(s)

S/N	Qty	Descriptions	Amount	
LABOUR & OTHER CHARGES:-				
1		To panel beat and renewal of all necessary damaged body parts	1200	800 ✓
2		To realign headlamp focus	60	30 ✓
3		To check wiring and rewire	60	30 ✓
4		To remove and reinstall radiator and a/c condenser	160	×
5		To vacuum and refill a/c refrigerant R134A	120	×
6		To reset collision system setting fault code	150	×
7		to perform 4 wheel alignment	100	60 ✓
8		To remove and reinstall front parking sensor	120	30 ✓
9		to remove and reinstall front rh undercarriage item	250	200 ✓
10		To anti-rust	100	30 ✓
11		To putty and spray-paint of affected areas	1200	900 ✓
			3520	2080

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Steve (LKK)
 15/05/20, 12.00 pm
 Without Prejudice
 L/S
 Resurvey After Spray
 7 repair days

P - 3801
 N - 550
 L - 2080
 6431
 L/S - 5144.80
 = 5150

Grand - Total 3520