

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To:	MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Jasmine Lok Kheng Kwei	Date:	20 May 2020

**Preliminary Advice**

Insured Vehicle No	:	SJH6484L		
TP Vehicle No	:	SFX8336G	Accident Date	: 12/05/2020
Make	:	TOYOTA C-HR	Assignment Date	: 14/05/2020
Date of Inspection	:	15/05/2020	Est. Duration of Repair	: 7.00
Inspection At	:	CAR PRO AUTO (HQ) BLK 6 YEW TEE INDUSTRIAL ESTATE 399-J, WOODLANDS ROAD SINGAPORE 678008		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 13,355.75
Revised Amount	:	S\$ 6,431.00
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 6,431.00
Lump Sum Repair		:

**Total Loss Consideration**

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

**Remarks**

- (      ) The vehicle is economical/not economical for repair.
- ( X ) The above survey was conducted on a 'without prejudice' basis.