

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 13-May-20

INSURANCE: FCI

MODEL: HYUNDAI IONIC

VEHICLE NO.: SHB4140Y

Description	Qty	List Price	Amount	
Boot Lid <i>1st / Dented</i>	1	\$ 2,480.40	\$ 2,480.40	✓
Boot Lid Rubber <i>deformed</i>	1	\$ 187.40	\$ 187.40	✓
Boot Lid Hinge (LH/RH) <i>HH</i>	2	\$ 71.30	\$ 142.60	X
Boot Lid Absorber (LH/RH) <i>HH</i>	2	\$ 86.70	\$ 173.40	X
Boot Lid Lock Upper <i>Down</i>	1	\$ 224.00	\$ 224.00	✓
Boot Lid 'H' Emblem <i>Heu</i>	1	\$ 28.00	\$ 28.00	✓
Emblem-Hybrid <i>Heu</i>	1	\$ 24.30	\$ 24.30	✓
Emblem-Ioniq <i>Heu</i>	1	\$ 31.30	\$ 31.30	✓
BOOT HANDLE <i>HH</i>	1	\$31.80	\$31.80	X
Boot Lid Lamp(LH/RH) <i>Crack</i>	2	\$ 794.40	\$ 1,588.80	✓
Boot Lid Trimboard <i>HH</i>	1	\$ 259.70	\$ 259.70	X
Boot Lid Trimboard Clips (10pcs) <i>HH</i>	1	\$ 11.00	\$ 11.00	X
Boot Lid Trimboard, Centre <i>HH</i>	1	\$ 159.60	\$ 159.60	X
Boot Lid Trimboard SIDE (LH/RH) <i>HH</i>	2	\$ 92.50	\$ 185.00	X
Boot Lid Trimboard REAR <i>HH</i>	1	\$ 124.80	\$ 124.80	X
Rear Windscreen moulding <i>Heu</i>	2	\$ 186.30	\$ 372.60	✓
Rear Bumper <i>Dented / torn</i>	1	\$ 459.40	\$ 459.40	✓
Rear Bumper Reinforcement <i>broken</i>	1	\$ 394.80	\$ 394.80	✓
Rear Bumper Reinforcement Bracket (LH/RH) <i>1st / Ruptured</i>	2	\$ 188.10	\$ 376.20	✓
Antenna Assy-SMARTK <i>Dented / mostly broken</i>	1	\$ 689.50	\$ 689.50	✓
Rear Bumper Centre Moulding Assy <i>Dented / torn</i>	1	\$ 451.25	\$ 451.25	✓
Rear Bumper Lower Centre Moulding Assy <i>mostly broken</i>	1	\$ 47.50	\$ 47.50	✓
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10	X
Rear Bumper Side retainer (LH/RH) <i>svc</i>	2	\$ 85.80	\$ 171.60	X
Rear Bumper Cover Clips <i>Heu</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Under Centre <i>cracked</i>	1	\$ 123.85	\$ 123.85	✓
Rear Bumper Side Under(LH/RH) <i>HH</i>	2	\$ 123.10	\$ 246.20	X
Rear Bumper Rear Hook <i>HH</i>	1	\$ 94.60	\$ 94.60	X
Rear Bumper Reflector Lamp(LH/RH) <i>HH</i>	2	\$ 82.90	\$ 165.80	X
Rear Bumper Towing Cover <i>HH</i>	1	\$ 98.80	\$ 98.80	X
Rear Bumper Reserve Light (Parking Brake Light) <i>Socket broken</i>	1	\$ 328.60	\$ 328.60	✓
Licence Lamp (LH/RH) <i>HH</i>	2	\$ 85.30	\$ 170.60	X
Licence Lamp WIRE <i>HH</i>	1	\$ 135.80	\$ 135.80	X
Tail Lamp(LH/RH) <i>mostly crack</i>	2	\$ 870.40	\$ 1,740.80	✓
Tail Lamp Quarter Panel(LH/RH) <i>HH</i>	2	\$ 208.90	\$ 417.80	X
Rear Panel <i>Bnc</i>	1	\$ 532.00	\$ 532.00	✓
Rear Panel Garnish <i>1st / deformed</i>	1	\$ 346.80	\$ 346.80	✓
Spare Tyre Holder <i>HH</i>	1	\$ 223.10	\$ 223.10	X
Spare Wheel Lock Nut <i>Crack / broken</i>	1	\$ 89.50	\$ 89.50	✓
Spare Tyre Panel <i>Bnc</i>	1	\$ 892.50	\$ 892.50	✓
Member Assy-Rear Floor Centre <i>HH</i>	1	\$ 863.50	\$ 863.50	X
Panel Assy-Rear Floor Side (LH/RH) <i>HH</i>	2	\$ 39.40	\$ 78.80	X

Rear Floor Chassis Member (RH) <i>NN</i>	1	\$ 1,863.40	\$ 1,863.40	X
Rear tray tools box RH <i>1st / deformed</i>	1	\$ 675.30	\$ 675.30	X
Rear tray tools box LH <i>1st / deformed</i>	1	\$ 693.20	\$ 693.20	X
REAR TRAY LUGGS CENTER <i>1st / deformed</i>	1	\$ 354.20	\$ 354.20	X
Exhaust Pipe Insulator <i>1st</i>	1	\$ 235.00	\$ 235.00	X
Exhaust Silencer <i>Replaced</i>	1	\$ 943.50	\$ 943.50	X
Exhaust Pipe Hanger <i>1st</i>	1	\$ 29.20	\$ 29.20	X
Rear Fender(RH) <i>Replaced</i>	1	\$ 1,768.30	\$ 1,768.30	X
Rear Fender SHIELD REAR PIECE (LH / RH) <i>1st</i>	1	\$ 173.60	\$ 173.60	X
Rear Fender SHIELD Fit Piece (RH) <i>1st</i>	1	\$ 165.50	\$ 165.50	X
Rear Fender Air-Duct (RH) <i>1st</i>	1	\$ 87.30	\$ 87.30	X
Rear Wiring Assy <i>1st</i>	1	\$ 1,521.50	\$ 1,521.50	X

SUB TOTAL

\$ 23,834.10

LESS 20%

\$ 4,766.82

DISCOUNTED TOTAL

\$ 19,067.28

Boot Lid Comfort Logo & Tel No. Sticker <i>1st</i>	SN	1	\$ 35.00	\$ 35.00	X
Boot Lid Comfort Cablink Tel No. Sticker <i>1st</i>	SN	1	\$ 30.00	\$ 30.00	X
Rear No. Plate + Trim Cover <i>1st</i>	SN	1	\$ 45.00	\$ 45.00	X
Rear Windscreen Sealant <i>1st</i>	SN	2	\$ 46.00	\$ 92.00	X
Rear Bumper Rubber Mat <i>1st / deformed</i>	SN	1	\$ 50.00	\$ 50.00	X
Rear Bumper Reverse Sensor <i>1st</i>	SN	1	\$ 180.00	\$ 180.00	X
SPARE TYRE PANEL TOP COVER SILICON <i>1st</i>	SN	1	\$ 250.00	\$ 250.00	X

SUB TOTAL

\$ 682.00

Labour Charge

Panel Beating	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____	1	\$1,800.00	\$1,800.00	1000/-
Spray Painting Charge		1	\$1,400.00	\$1,400.00	800/-
Wiring Charge		1	\$160.00	\$160.00	30/-
Tuff Kote		1	\$160.00	\$160.00	40/-
Towing Charge		1	\$80.00	\$80.00	40/-
Remove/Refix Cushion & Upholstery Rear		1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass		1	\$120.00	\$120.00	80/-
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00	40/-
Remove/Refix Fuel Tank		1	\$80.00	\$80.00	40/-
Remove/Refix Exhaust Pipe		1	\$80.00	\$80.00	60/-
Diagnostic & Resetting To Erase Fault Code		1	\$550.00	\$550.00	700/-

TOTAL LABOUR

\$4,700.00

ESTIMATE TOTAL

\$ 24,449.28

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

15/05/2020 @ 0900hrs

Not Attached

7/Part 7 days.

↑
LKK Auto

Photo after/before
repair point with
damaged parts.