



新 福 德 車 廠

NEW HOCK TECK MOTOR WORKSHOP

1 Kaki Bukit Ave 6, Blk C #01-43 Autobay@Kaki Bukit, Singapore 417883

Email: n60_newhockteck@hotmail.com

Tel: 6747 9241 Fax: 6741 7276

RCB No.: 52989088K GST Reg No.: M90368118A

29th Apr 2016

NURUM MOBNUR RAHMAN

Blk C, 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Chim
Jes.

Accident date: 27th Apr 2016

Estimate repair cost for vehicle no: SJW4950S CHEVROLET CRUZE 1.6L '10

S/n	Qty	Items	U/price	Amount
1	1	Front L/H Head Lamp <i>cut</i>		\$961.20 ✓
2	1	Front L/H Head Lamp Lower Bracket <i>Mem</i>		\$19.10 +
3	1	Front Bumper <i>Det</i>		\$912.50 ✓
4	1	Front Bumper L/H Side Retainer <i>per</i>		\$43.70 ✓
5	10	Front Bumper Clips <i>on</i>	\$6.50	\$65.00 30
6	1	Front Bumper L/H Fog Lamp <i>cracked</i>		\$261.60 2 ✓
7	1	Front Bumper L/H Fog Lamp Cover <i>cut</i>		\$114.60 ✓
8	1	Front Bumper Reinforcement <i>3 x 1/2</i>		\$871.10 +
9	1	Front Bumper Inner Sponge <i>1 x 1/2</i>		\$300.00 +
10	1	Front L/H Fender <i>Det</i>		\$614.40 ✓
11	1	Front L/H Fender Cowling <i>3 x 1/2</i>		\$118.80 +
12	10	Front L/H Fender Cowling Clips <i>1 x 1/2</i>	\$6.50	\$65.00 +
13	1	Front Lower Arm <i>2</i>		\$584.70 +
14	1	Front Knuckle Arm <i>1 x 1/2</i>		\$356.40 +
15	1	Front Knuckle Arm Bearing <i>1 x 1/2</i>		\$441.10 +
16	1	Front L/H Shock Absorber <i>1</i>		\$351.70 +
			Subtotal :-	\$6,080.90

2938
264420

S/n	Qty	Items / S.Nett	U/price	Amount
17	1	Front L/H Rim <i>Not new</i>		\$750.00 +
			Subtotal :-	\$750.00

Labour charges

To remove & refit L/H undercarriage

\$380.00 X

To check wheel alignment

\$150.00 X

Tuff kote

\$150.00 30

To check wiring

\$50.00 30

Panel beating

\$850.00 400

Spray painting

\$750.00 400

Subtotal :- \$2,330.00

Total:- \$9,160.90

L/S Adrian King
04/05/16
OK Days

total: 3850420

L/S: 28K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

28K