



Carway Enterprise

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934
 Business Reg. No. 53096404W GST Reg. No. M90365035R
 ☎ 67440777 ☎ 67442377 💻 <http://www.carway.com.sg>

Your Satisfaction is our Success!

Estimate Quotation

Quotation No	2020-May/01
Date	12/5/2020
Vehicle No	SJR3651M
Make / Model	Toyota Vios

Jasper

To: AXA
 Address: 8 Shenton Way #27-01 AXA Tower Singapore 068811

Qty	DESCRIPTION	UNIT	Amount	
	Items			
1 pc	front bumper <i>Distorted</i>		\$ 497.00	✓
2 pcs	front bumper side retainer <i>RH and</i>	\$ 78.00	\$ 156.00	38
1 set	front bumper clips <i>in</i>		\$ 30.00	✓
1 pc	front bumper lower spoiler <i>curled</i>		\$ 485.00	✓
1 pc	front bumper tow hook cover <i>del</i>		\$ 35.00	✓
1 pc	front bumper inner sponge <i>del</i>		\$ 186.00	✓
1 pc	front bumper reinforcement bar <i>Best</i>		\$ 475.00	✓
1 pc	front grille <i>curled</i>		\$ 356.00	256
1 pc	front grille chrome moulding <i>new</i>		\$ 197.00	x
1 pc	front bumper lower grille <i>new</i>		\$ 125.00	x
1 pc	front engine lower cover <i>new</i>		\$ 180.00	✓
1 set	front engine lower cover clips <i>new</i>		\$ 30.00	✓
1 pc	front grille "centre" emblem <i>new</i>		\$ 110.00	48
2 pc	headlamp <i>curled</i>	\$ 580.00	\$ 1,160.00	✓
1 pc	o/s front bumper fog lamp <i>curled</i>		\$ 198.00	2
1 pc	o/s front bumper fog lamp garnish <i>del</i>		\$ 125.00	25
1 pc	o/s front bumper fog lamp outer chrome garnish <i>curled</i>		\$ 78.00	45
1 set	o/s front fender <i>Distorted</i>		\$ 658.00	425
1 pc	o/s front fender inner shield <i>new</i>		\$ 245.00	163
1 set	o/s front fender inner shield clip <i>new</i>		\$ 30.00	2
1 pc	"VVTI" emblem <i>new</i>		\$ 63.00	45
1 pc	n/s side mirror <i>del</i>		\$ 689.00	x
1 pc	bonnet <i>Distorted</i>		\$ 685.00	✓
2 pc	bonnet hinge <i>new</i>		\$ 174.00	x
1 pc	front support panel <i>new</i>	\$ 87.00	\$ 985.00	✓
1 set	bonnet insulator clip <i>new</i>		\$ 30.00	✓
1 pc	o/s front door <i>del</i>		\$ 987.00	✓
2 pcs	o/s front door hinge <i>new</i>	\$ 98.00	\$ 196.00	x
1 pc	o/s front fender quarter garnish <i>new</i>		\$ 78.00	x
1 pc	o/s front sport rim <i>new</i>		\$ 780.00	500 (sw)
1 pc	o/s front shock absorber <i>Best</i>		\$ 587.00	341
1 pc	o/s front knuckle arm <i>del</i>		\$ 595.00	442
1 pc	o/s front knuckle arm bearing <i>new</i>		\$ 197.00	✓
1 pc	o/s front lower arm <i>Best</i>		\$ 587.00	381
1 pc	washer tank <i>del</i>		\$ 235.00	142
1 pc	aircon condenser <i>new</i>		\$ 897.00	x
1 pc	washer tank motor <i>new</i>		\$ 287.00	x

Front RH tyre Punctured 180 (SW) ✓

*7538
 5653.50 S.W. 680*



Carway Enterprise

53 Ubi Avenue 1, #03-01, Paya Ubi Industrial Park, Singapore 408934

Business Reg. No. 53096404W

GST Reg. No. M90365035R

☎ 6744 0777

☎ 6744 2377

💻 <http://www.carway.com.sg>

Your Satisfaction is our Success!

Labour Charge			
1	to dismantle damaged parts, panel beat, repair	\$	1200 900
2	to putty and spray painting on affected area	\$	1400 1100
3	anti rust	\$	150.00 80
4	R&R wiring	\$	80.00 30
5	R&R aircon	\$	150.00 120
6	R&R undercarriage	\$	300.00 220
7	wheel alignment	\$	150.00 80
8	towing charge	\$	80.00 60
9	transfer door	\$	80.00 ✓
			2670
Subtotal:		\$	16,298.00

Authorised Signature

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:.

Adrian Lj
h/s 15/05/20

00 Days.

total 9003.50

h/s 7.2K

7.2K