

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
 BEDOK NORTH AVE 4,
 #01-2008/10/12 SINGAPORE 489977
 TEL : 6441 5655 FAX : 6441 5355/6243 8121
 R.O.C No : 200104141D GST Reg. No. 20-0104141-D

not Authorized
 Name
 29/6/20
 1/5 S
 the photo of Affected
 4 days

ESTIMATE BILL

TO : 201018630W
 INDUSPRINT PTE LTD
 BLK 164 KALLANG WAY
 02-25
 SINGAPORE 349248
 TEL : 64456006 FAX : 64497634
 PH :
 ATTN :

Number : EB00005477
 Date : 11/05/2020
 Case No : AD00011112
 Vehicle No : GY7878Z
 Chassis : VM20102506
 Year of Mfr : 2016
 Policy No : 5100894787-01
 Model : NISSAN NV200 DX-2
 1.6 AUTO

Term: 30%

| Sn | DESCRIPTION | QTY | U_PRICE | DISC | AMOUNT |
|--|--|----------------|----------|-------------|-------------|
| 1 | REAR BUMPER LOWER <i>to be</i> | 1.0 | 481.10 | 10 | 432.99 |
| 2 | TAILGATE <i>30dB</i> | 1.0 | 1,724.60 | 10 | 1,552.14 |
| 3 | TAILGATE EMBLEM <i>rec</i> | 1.0 | 55.10 | 10 | 49.59 |
| 4 | TAILGATE LOGO - NV200 <i>rec</i> | 1.0 | 65.90 | 10 | 59.31 |
| 5 | TAILGATE LOGO - VANETTE <i>rec</i> | 1.0 | 65.90 | 10 | 59.31 |
| 6 | TAILGATE STICKER - MAXIMUM LOAD <i>rec</i> | 1.0 | 32.50 | 10 | 29.25 |
| 7 | END PANEL <i>sp/bent</i> | 1.0 | 152.40 | 10 | 137.16 |
| 8 | REAR FENDER LH <i>1-1</i> | 1.0 | 1,709.70 | 10 | 1,538.73 |
| 9 | REAR FENDER RH <i>1-1</i> | 1.0 | 1,709.70 | 10 | 1,538.73 |
| 10 | REAR MUFFLER - UNCONFIRMED <i>1-1</i> | 1.0 | | 10 | |
| Nett Price - Parts Sub Total | | | | | 5,397.21 |
| 11 | REVERSE SENSOR <i>shallow</i> | 1.0 | 320.00 | 0 | 320.00 |
| 12 | WINDSCREEN SEALANT <i>rec</i> | 2.0 | 24.00 | 0 | 48.00 |
| 13 | TAILGATE STICKER - 70KM/H <i>rec</i> | 1.0 | 30.00 | 0 | 30.00 |
| 14 | TAILGATE STICKER <i>rec</i> | 4.0 | 80.00 | 0 | 320.00 |
| Special Nett Price - Parts Sub Total | | | | | 718.00 |
| Parts Total | | | | | 6,115.21 |
| 15 | LABOUR TO REMOVE & REFIT NECESSARY PARTS | 1.0 | 1,200.00 | 0 | 6001,200.00 |
| 16 | SPRAY PAINT ON THE AFFECTED AREAS | 1.0 | 1,000.00 | 0 | 6001,000.00 |
| 17 | ANTI-RUST COATING | 1.0 | 180.00 | 0 | 50 180.00 |
| 18 | TO REMOVE & REFIT WINDSCREEN | 1.0 | 180.00 | 0 | 100 180.00 |
| 19 | TO REMOVE & REFIT REVERSE SENSOR | 1.0 | 150.00 | 0 | 50 150.00 |
| Labour 1 Sub Total | | | | | 2,710.00 |
| SINGAPORE DOLLARS : NINE THOUSAND FOUR HUNDRED FORTY-TWO AND CENTS NINETY-SEVEN ONLY | | | | Less Excess | 0.00 |
| | | | | SUBTOTAL | 8,825.21 |
| | | | | GST 7.00% | 617.76 |
| | | | | TOTAL | 9,442.97 |

✓
✓
✓
✓
✓
✓
✓
✓
✓
✓
✓
X
X
X
200
40
10
?

LKK Auto Consultants hence notify
 the Repairer of the following:

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Date of accident : 07/05/2020
 ROAD)
 E. & O. E.

DELTA ROAD TOWARDS TIONG BAHRU

HOCK WAH MOTOR WORKSHOP PTE LTD

25775
 102
 2319.75
 3969.75

CUSTOMER SIGNATURE _____ AUTHORIZED SIGNATURE _____

* N = Item not subjected to GST