



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Seema Devi	Cust No/Name	/Seema Devi
Blk 989d Jurong West Street 93	Reg No/Reg Date	SLW3182A / 07/02/201
#11-661	Date In/Mileage	/ 0
Singapore 644989	Chassis No	MMBSTA13AJH001457
Contact No Mobile: 82202393	Engine No	3A92UGR2467
	Make/Model	MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim	P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	28/03/2020/ 13:10	QUE	261 / Edwin Caina	52612			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3300 5500.00
RENEW RR BUMPER , BOOTLID , RR END PNL , LHR FENDER & RHR FENDER								
REPAIR RR FLR PNL & RR CHASSIS								
E PNT98000								2100 2940.00
RESPRAY RR BUMPER , BOOTLID , RR FLR PNL , RR END PNL , LHF FENDER ,								
RHR FENDER & RR CHASSIS								
E PNT88000								✓ 275.00
REMOVE & REFIT BOOTLID COMPONENT								
A 13900099								✗ 550.00
REMOVE & REFTI FUEL ASSY TO GIVE WAY FOR REPAIR								
E PNT88000								✓ 275.00
REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & SEAT TO FACILITATE REPAIR								
A 54900099								30 50.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								✓ 200.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								160 250.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								160 200.00
SUPPLY BODY PNL SEALANT								
E PNT88000								✓ 240.00
REMOVE & REFIT RR WINDSCREEN GLASS								
M SUNDRY								✓ 80.00
SUPPLY RR WINDSCREEN SEALANT								
M SUNDRY								47 ✓ 80.00
SUPPLY RR NUMBER PLATE WITH CASING								
E PNT88000								80 100.00
REMOVE & REFIT REVERS SENSOR								
M SUNDRY								1W ✓ 220.00
SUPPLY REVERSE SENSOR								
M SUNDRY								1W ✓ 40.00
SUPPLY C&C BADGE								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
Seema Devi	Cust No/Name /Seema Devi
Blk 989d Jurong West Street 93	Reg No/Reg Date SLW3182A / 07/02/201
#11-661	Date In/Mileage / 0
Singapore 644989	Chassis No MMBSTA13AJH001457
Contact No Mobile: 82202393	Engine No 3A92UGR2467
	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	28/03/2020/ 13:10	QUE	261 / Edwin Caina	52612
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M FACE,RR BUMPER		1.00	748.00	00.00	de 748.00
M BRACKET,RR BUMPER,LH		1.00	28.00	00.00	de 28.00
M BRACKET,RR BUMPER,RH		1.00	28.00	00.00	de 28.00
M CLIP,RR BUMPER		4.00	4.00	00.00	de 16.00
M REFLECTOR LH		1.00	23.00	00.00	? 23.00
M REFLECTOR RH		1.00	23.00	00.00	? 23.00
M PANEL,RR END		1.00	425.00	00.00	? 425.00
M TRIM,RR END		1.00	66.00	00.00	? 66.00
M BOARD,TRUNK ROOM FLOOR		1.00	195.00	00.00	? 195.00
M MUD GUARD,RR LH		1.00	41.00	00.00	x 41.00
M MUD GUARD,RR RH		1.00	41.00	00.00	x 41.00
M BUZZER,KEYLESS OPERATIO,RR		1.00	91.00	00.00	? 91.00
M ANT,KEYLESS OPERATION,RR		1.00	96.00	00.00	? 96.00
M COVER,RR VENTILATOR		1.00	40.00	00.00	? 40.00
M DUCT,RR VENTILATOR		1.00	30.00	00.00	? 30.00
M PANEL,QTR,QTR LH		1.00	755.00	00.00	Ry 755.00
M PANEL,QTR,QTR RH		1.00	763.00	00.00	bul 763.00
M PANEL,RR COMB LAMP HSG,LH		1.00	60.00	00.00	Ry 60.00
M PANEL,RR COMB LAMP HSG,RH		1.00	60.00	00.00	bt 60.00
M EXTN,QTR PANEL,UPR QTR LH		1.00	118.00	00.00	Ry 118.00
M EXTN,QTR PANEL,UPR QTR RH		1.00	118.00	00.00	? 118.00
M PANEL,TRUNK LID		1.00	791.00	00.00	bt 791.00
M WEATHERSTRIP,TRUNK LID		1.00	157.00	00.00	? 157.00
M HINGE,TRUNK LID,LH	phlt*	1.00	203.00	00.00	bt 203.00
M HINGE,TRUNK LID,RH		1.00	203.00	00.00	bt 203.00
M LATCH,TRUNK LID		1.00	218.00	00.00	? 218.00
M STRIKER,TRUNK LID LATCH		1.00	20.00	00.00	? 20.00
M MARK,THREE-DIA		1.00	69.00	00.00	ne 69.00
M MARK,ATTRAGE		1.00	21.00	00.00	ne 21.00
M GARNISH,RR END PANEL		1.00	336.00	00.00	? 336.00
M LAMP ASSY,COMB,RR LH		1.00	335.00	00.00	ne 335.00
M LAMP ASSY,COMB,RR RH		1.00	335.00	00.00	ne 335.00
M STOPPER,WINDSHIELD GLASS		2.00	3.00	00.00	ne 6.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Seema Devi	Cust No/Name /Seema Devi
Blk 989d Jurong West Street 93	Reg No/Reg Date SLW3182A / 07/02/201
#11-661	Date In/Mileage / 0
Singapore 644989	Chassis No MMBSTA13AJH001457
Contact No Mobile: 82202393	Engine No 3A92UGR2467
	Make/Model MIT/18MY ATTRAGE 1.2 CVT
	Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	28/03/2020/ 13:10	QUE	261 / Edwin Caina	52612
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
M SPACER,RR WINDOW	3.00	9.00	00.00	27.00	net
M DECAL,MIVEC	1.00	36.00	00.00	36.00	net

Estimate

SURVEYOR NAME: Taufik 9749549SURVEYOR SIGNATURE: [Signature]DATE: 19/5/20 @ 1230 WPREMARKS: *Resurvey before paint.09 daystaufik @ lkkauto.comsur @ lkkauto.com

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by
 • Third party survey is on a "Without Prejudice" basis
 • No legal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorized signatory and company stamp

7% GST on	Nett	17,522.00
	17522.00	1226.54
Total Payable		18,748.54

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.