




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL		Ref : CS3/SMO19017325/Fvf3s2-1		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623		Date : 27-05-2020		
		Code : SMO		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLA 8057L	Veh. Inspected	FBC 6779H	
Policy No.	D19MTPV01003167	Coverage (\$)	0.00	
Claim No.	CMTD1904546	Excess (\$)	0.00	
Assign From	GNOH PAU LOONG	Assign Date	15/05/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CB400	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	NC421002158	Colour	BLACK	
Odometer	88108	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/60 R17	BRIDGESTONE	3 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	BRIDGESTONE	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION AND O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	28/09/2019	Inspection Date	02/10/2019	
Survey held at	HL CYCLE PL 1 KAKI BUKIT AVE 6 #02-58 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		