

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel 6366 2323 Fax 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35707

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/01/0390/2020/NS
Date : 13-May-20

52225-60

Vehicle NOT IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Samuel Ee Cheng En
Address : 774 Bedok Reservoir View
#11-115
Singapore 470774
Telephone : HP +65 98711703
Type of Claim : Own Damage Claim
Policy No. : 2070037067
Vehicle No : **SMS 8841 H**
Model Code : Audi A3 sportsback 1.0 TFSI
Model / Year : Mar-20
Engine No : CHZ C38868
Chassis No : WAUZZZ8V1LA049446
Mileage : 2151KM
Date In : 13-May-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-May-20
Place of Accident : PIE Bedok North Avenue 3 Entrance

Premium Automobiles

1000 Highway 101
St. John's, NL A1A 1A1

Telefax

Estimated Labour Charges for Accident Vehicle: SMS 8841 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To tow and recover vehicle from scene of accident.	S/N \$ X 280.00	X
2	To carry out first measurement test on car o-liner.	S/N \$ 800.00	? X
3	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ ✓ 360.00	✓ 360
4	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ ✓ 1,200.00	✓ 1200
5	To remove centre console, instrument panels and clusters. Renew dashboard, both frontal airbags, slip ring. Transfer old fittings. Renew seat belts and control unit, pillar trims, roof lining, both curtain airbags and knee airbag.	S/N \$ ✓ 3,600.00	✓ 3600
6	To remove and reinstall engine assy with gearbox assy to facilitate car o-liner repairs.	S/N \$ 2,800.00	? X
SUB TOTAL LABOUR CHARGES		: \$ 9,040.00	

Premium Automobiles

55, Ulu Road 2, Singapore 408699
Tel: 6362 2321 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle, SMS 8841 H

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
7	To remove and reinstall front suspension assy with subframe to facilitate car o-liner repairs. Inspect for damages and renew is necessary.	S/N \$ 2,400.00	? X
8	To place vehicle on car o-liner	S.N \$ 2,400.00	? X
9	To dismantle lhs front door panel trim. To remove and reinstall lhs wing mirror assy.	S/N \$ ✓ 350.00	250. 280
10	To dismantle and renew front bumper, bonnet, lhs front ender, both headlights. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all prts removed.	\$ ✓ 5,600.00	3250. 3250
11	To respray front bumper, lhs front fender, bonnet, engine compartment and lhs front door. AAA Pillar LH	\$ ✓ 4,700.00	2750. 2750
12	To carry out pre-repair diagnostic check and post repair diagnostic check.	S/N \$ ✓ 384.00	✓ 384
TOTAL LABOUR CHARGES		: \$ 24,874.00	

Premium Automobiles

Sole Road 1, 408600
Tel: 0866 2823 Fax: 0841 1183

Telefax

Material List for Accident Vehicle Regn No. SMS 8841 H

S/N	Parts Description	Damage Parts & Prices S/Nett	Remarks
1	FRONT BUMPER <i>Distorted</i>	\$ 1,756.00 ✓	✓ 1404.80
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ X 176.00 ✓	
3	FRONT BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$ X 72.00 x	
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$ X 151.00 x	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$ X 280.00 x	
6	FRONT BUMPER CLOSING ELEMENT - LH / RH <i>new</i>	2 \$ X 560.00 x	
7	RADIATOR GRILLE <i>new</i>	\$ 1,338.00 ✓	✓ 1070.40
8	RADIATOR GRILLE CLOSING ELEMENT <i>new</i>	\$ 180.00 ✓	✓ 143.60
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$ X 354.00 x	
10	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>new</i>	\$ 681.00 ✓	✓ 544.8
11	FRONT BUMPER FOAM FILLER PIECE <i>new</i>	\$ 178.00 ✓	✓ 142.4
12	FOAM FILLER PIECE COVER <i>Damaged</i>	\$ 114.00 ✓	✓ 91.60
13	AIRCON STICKER <i>new</i>	NEC \$ 7.00 ✓	✓ 5.36
14	CAUTION SIGN STICKER <i>new</i>	NEC \$ 13.00 ✓	✓ 10.24
15	SIGNAL HORN - LH HIGH TONE <i>new</i>	\$ 188.00 ?	✓ 150
16	SIGNAL HORN - RH LOW TONE <i>new</i>	\$ X 188.00 ?	
17	FRONT FENDER - LH <i>Buckled</i>	\$ 802.00 ✓	✓ 641.20
18	FRONT FENDER ATTACHMENT PARTS <i>new</i>	\$ X 68.00 ?	
19	FRONT FENDER BRACET - LH <i>new</i>	\$ X 26.00 x	
20	FRONT FENDER BRACKET - LH <i>new</i>	\$ 45.00 ✓	35.36
SUB TOTAL SPARE PARTS CHARGES		: \$ 7,177.00	

Premium Automobiles

100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000

Telefax

Material List for Accident Vehicle Regn No. SMS 8841 H

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
21	FRONT ENDER BRACE	\$	X 90.00	✓
22	FRONT ENDER SEAL - LH	\$	X 32.00	✓
23	FRONT ENDER CLOSING ELEMENT - LH	\$	X 58.00	✓
24	WHEEL HOUSING LINER - LH	\$	X 244.00	✓
25	WHEEL HOUSING LINER - RH	\$	X 159.00	✓
26	WHEEL HOUSING LINER ATTACHMENT PARTS	\$	X 54.00	✓
27	BONNET	\$	✓ 2,581.00	✓ 2064.80
28	BONNET ATTACHMENT PARTS	\$	X 155.00	✓
29	BONNET LID HINGE - LH / RH	2 \$	✓ 116.00	✓ 91.84
30	BONNET COVER - LH / RH	2 \$	✓ 78.00	✓ 60.96
31	BONNET GAS FILLED STRUT	\$	X 112.00	✓
32	BONNET EDGE PROTECTION - FRONT	\$	✓ 26.00	✓ 20.80
33	BONNET CATCH HOOK	\$	✓ 84.00	✓ 67.12
34	BONNET STRIKER - LH / RH	2 \$	✓ 208.00	✓ 165.60
35	WATER BOX SEAL ADAPTER - LH / RH	2 \$	X 26.00	✓
36	BONNET CATCH HOOK	2 \$	✓ 60.00	✓ 47.44
37	BONNET LID LOCK	2 \$	✓ 403.00	✓ 322.4
38	CONNECTOR HOUSING BRACKRT	2 \$	X 12.00	✓
39	BONNET BOWDEN CABLE - CENTRE	2 \$	✓ 54.00	✓ 43.20
40	BONNET LID LOCK CABLE	\$	X 69.00	✓
SUB TOTAL SPARE PARTS CHARGES		:	<u>\$ 4,621.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMS 8841 H

S/N	Parts Description		Damage Parts & Prices	
			S/Nett	Remarks
41	BONNET SOUND ABSORBER <i>crushed</i>	\$	✓ 207.00	✓ 165.2
42	PLENUM CHAMBER COVER <i>new</i>	\$	✗ 159.00	✗
43	LED HEADLIGHT - LH / RH <i>crushed</i>	2 \$	10,386.00	✓ 8308.8
44	MAIN LIGHT ELECTRONICS POWER MODULE - LH <i>shorted</i>	\$	✓ 714.00	? 571.2
45	LED WITH HEAT SINK - LH <i>Not Nec</i>	\$	✗ 689.00	?
46	LIGHT CONTROL SYSTEM CONTROL UNIT <i>Not Nec</i>	\$	✗ 524.00	?
47	HEADLAMP HOUSING REPAIR KIT <i>new</i>	\$	✓ 124.00	✓ 99.20
48	HEADLIGH HOSE - LH <i>new</i>	\$	✗ 38.00	✗
49	LIFT CYLINDER - LH / RH <i>Not Nec</i>	2 \$	✗ 268.00	?
50	LIFT CYLINDER HOSE <i>new</i>	\$	✗ 64.00	✗
51	WASH WATER RESERVOIR <i>Deformed.</i>	\$	✓ 190.00	? 151.6
52	WASH WATER STRAINER <i>new</i>	\$	✗ 20.00	✗
53	WASH WATER END CAP <i>new</i>	\$	✗ 20.00	✗
54	LOCK CARRIER <i>Crushed</i>	\$	✓ 685.00	✓ 547.60
55	EXTERNAL TEMPERATURE SENSOR <i>Not Nec</i>	\$	✗ 55.00	?
56	TEMPERATUE SENSOR BRACKET <i>Damaged.</i>	\$	✓ 18.00	? 13.68
57	AIRCON CONDENSER <i>Bent</i>	\$	✓ 519.00	✓ 415.2
58	REFRIGERANT LINE <i>Not Nec</i>	\$	✗ 471.00	?
59	REFRIGERANT LINE <i>Not Nec</i>	\$	✗ 613.00	?
60	REFRIGERANT LINE BRACKET <i>Not Nec</i>	\$	✗ 25.00	?
TOTAL SPARE PARTS CHARGES		:	\$15,799.00	

Premium Automobiles

25, 06 Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMS 8841 H

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
61	DUAL CLIP <i>Not Nec</i>	\$ X 29.00	
62	RADIATOR <i>Dented</i>	\$ ✓ 932.00	✓ 745.2
63	ADDITIONAL RADIATOR <i>Bent</i>	2 \$ ✓ 851.00	? 680.4
64	RADIATOR BRACKET <i>Not Nec</i>	2 \$ X 78.00	?
65	RADIATOR BUSH - LOWER <i>Not Nec</i>	2 \$ X 19.00	?
66	RADIATOR FAN <i>crushed</i>	\$ ✓ 1,070.00	✓ 856
67	RADIATOR AIR GUIDE - LH / RH <i>crushed</i>	2 \$ ✓ 46.00	✓ 36.32
68	RADIATOR AIR GUIDE - UPPER CENTRE <i>crushed</i>	\$ ✓ 12.00	✓ 8.88
69	RADIATOR HOSE - FRONT <i>Not Nec</i>	\$ X 232.00	?
70	AIR INTAKE AIR FILTER <i>cut</i>	\$ 256.00	✓ 211.60
71	AIR INTAKE AIR DUCT COVER <i>crushed</i>	\$ ✓ 28.00	✓ 21.84
72	AIR INTAKE AIR GUIDE <i>? crushed</i>	\$ ✓ 54.00	✓ 42.8
73	AIR INTAKE AIR GUIDE	\$ ✓ 19.00	✓ 14.8
74	WATER DRAINAGE HOSE <i>Not Damaged</i>	\$ ✓ 32.00	✓ 24.88
75	AIR INTAKE AIR GUIDE <i>crushed</i>	\$ ✓ 63.00	✓ 50.32
76	AIR INTAKE SEAL <i>Not</i>	\$ ✓ 13.00	✓ 10.24
77	AIR INTAKE MANIFOLD <i>Not Nec</i>	\$ X 131.00	?
78	AIR INTAKE MANIFOLD <i>Not Nec</i>	\$ X 600.00	?
79	AIR INTAKE SEAL <i>Not Nec</i>	\$ X 13.00	?
80	CHARGE AIR COOLER <i>Not</i>	\$ X 686.00	+
TOTAL SPARE PARTS CHARGES		: \$ 5,164.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMS 8841 H

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
81	CHARGE AIR COOLER SEAL <i>Not ne</i>	\$ X 13.00	+
82	CHARGE AIR COOLER SEAL	\$ X 13.00	+
83	THROTTLE VALVE CONTROL ELEMENT <i>?</i>	\$ X 996.00	+
84	THROTTLE VALVE SEAL <i>Not ne</i>	\$ X 16.00	+
85	ACTIVATED CHARCOAL CONTAINER <i>Not ne</i>	\$ X 302.00	?
86	STEERING WHEEL AIRBAG <i>Activated</i>	\$ ✓ 3,221.00	✓ 2576.8
87	AIRBAG UNIT <i>Activated</i>	\$ ✓ 4,330.00	✓ 3464.00
88	HEAD AIRBAG UNIT - LH / RH <i>Activated</i>	2 \$ ✓ 3,512.00	✓ 2809.60
89	KNEE AIRBAG UNIT <i>Activated</i>	\$ ✓ 1,756.00	✓ 1404.8
90	AIRBAG CONTROL UNIT <i>Not ne</i>	\$ ✓ 1,482.00	✓ 1185.60
91	ACCELERATOR SENSOR <i>Not ne</i>	X TBC	?
92	STEERING WHEEL <i>Not ne</i>	\$ ✓ 2,237.00	✓ 1789.60
93	DASHBOARD <i>Not ne</i>	\$ ✓ 4,014.00	✓ 3211.20
94	LOUDSPEAKER COVER <i>Not ne</i>	\$ X 88.00	+
95	AIR VENT - CENTRE <i>Not ne</i>	\$ X 142.00	+
96	TRAY - RH <i>Not ne</i>	\$ X 426.00	+
97	MOULDED HEADLINER <i>Not ne</i>	\$ ✓ 1,867.00	✓ 1493.60
98	THREE POINT SEATBELT - LH / RH <i>Activated</i>	2 \$ ✓ 2,080.00	✓ 1664.00
99	SEATBELT HEIGHT ADJUSTER <i>Activated</i>	2 \$ ✓ 368.00	✓ 147.20
100	FOLDING GRAB HANDLE - LH / RH REAR <i>Not ne</i>	2 \$ X 266.00	?
TOTAL SPARE PARTS CHARGES		:	\$26,863.00

Premium Automobiles

1180011, Singapore 408699
Fax: 6841 1180

Telefax

Material List for Accident Vehicle Regn No. SMS 8841 H

S/N Parts Description		Damage Parts & Prices		Remarks
		S/Nett		
101	FOLDING GRAB HANDLE - FRONT <i>Ne nec</i>	2	\$ X 266.00	7
102	A-PILLAR TRIM - LH / RH UPPER <i>lit</i>	2	\$ ✓ 302.00	241.60
103	B-PILLAR TRIM - LH / RH UPPER	2	\$ X 408.00	x
104	C-PILLAR TRIM - LH / RH UPPER <i>ne</i>	2	\$ X 172.00	✓
105	D-PILLAR TRIM - LH / RH UPPER <i>n</i>	2	\$ X 302.00	x
106	READY MIX COOLANT <i>ne</i>		\$ ✓ 169.00	134.72
107	FRONT NO PLATE <i>But</i>	S/N	\$ ✓ 60.00	60
108	SUNDRIES <i>Nec.</i>		\$ ✓ 700.00	23.84
TOTAL SPARE PARTS CHARGES		:	\$ 61,737.00	
TOTAL LABOUR CHARGES		:	\$ 24,874.00	
GRAND TOTAL		:	\$ 86,611.00	

All charges are not inclusive of GST.
Legend - marks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian L
14/05/20

: Not Authorised, 14 Days (Not inclusive of
car-o-liner usage.)
H.S.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

PA/OD/0390/2020/NS

Date

4-Jun-20

Service Advisor

Glory Tan

Pages

1 of 1

Regn No

SMS 8841 H

Model No

Audi A3 sportsback 1.0 TFSI

Quantity	Description
----------	-------------

Unit Price	Amount
------------	--------

Parts

1	Round connector 2 pin <i>coa</i>
---	----------------------------------

\$ 91.00	72.80
----------	-------

TOTAL

\$ 91.00

Raman

For Premium Automobiles Pte Ltd

Authorised Signature

*Subject to
insurance
approval*

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel: (65) 6366 2323 Fax: (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0390/2020/NS
Date 22-May-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SMS 8841 H
Model No Audi A3 sportsback 1.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Coolant pipe at	\$ 29.00	✓ 22.56

TOTAL \$ 29.00

Adrian Ling
22/05/20.

For Premium Automobiles Pte Ltd

Authorised Signature