

ESTIMATE FOR BMW F30 N13 316I

ITEM	ESTIMATION COST	REMARKS
Front Bumper M-Sport <i>List</i>	\$1,332.00	<i>SCR /</i>
Front Lip M-Sport	<i>700 S/N</i> \$1,420.00	<i>SCR /</i>
Left Head Lamp <i>List</i>	<i>2066</i> \$2,280.00	<i>SCR /</i>
Left Fender Front	\$751.20	<i>Repair</i>
Front Re-enforcement Bar	\$406.60	<i>X N1</i>
Front Left Lock	\$94.20	<i>X N1</i>
Front PCD Sensor	<i>S/N 250</i> \$395.90	<i>MIS /</i>
Front Left Fog Lamp <i>List</i>	\$295.30	<i>SCR /</i>
Front Left Fog Lamp Grille <i>List</i>	<i>SS</i> \$96.30	<i>SCR /</i>
Front Left Fender Cover	\$125.20	<i>X</i>
Front Left and Right Retainer	\$85.60	<i>X</i>
Front Left Head Lamp Module	\$1,995.55	<i>X</i>
Front Left DIS Lightbulb	\$311.40	<i>X</i>
Bonnet	\$1,370.67	<i>X</i>
Butterfly	\$160.50	<i>X N1</i>
Bonnet Hook	\$27.90	<i>X</i>
Front Left Bottom Rubber Garnish	\$112.35	<i>X</i>
Front Support Panel	\$180.85	<i>X</i>
Wiper Washer Front Left or Whole Set	\$171.20	<i>X</i>
Front Grille	\$160.00	<i>X</i>
Radiator	\$838.90	<i>X</i>
Condenser	\$1,105.30	<i>X</i>
Labour	\$1,000.00	<i>400</i>
Spray Part	\$1,000.00	<i>200 500</i>

\$15,716.92

Compay Name: LKKName of Surveyor: RASULContact Number: 90010068Date of Survey: 03/06/2020 @ 1440

Rem after repair
4 days
L/S

4 days

3560.88
950.00
900.00
5410.88
209
4328.70
L/S - 4,300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: