

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 35760

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0393/2020/NS
Date : 18-May-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : SLJ 2946 M

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Chan Eng Tiong Carl
Address : 193 Pavilion Circle
Singapore 658217
Telephone : (HP) +65 98313379
Type of Claim : Third Party Claims
Policy No. : 5096068900-02
Vehicle No : **SFS 989 B**
Model Code : A4 Sedan 2.0 TFSI
Model / Year : 30/7/2013
Engine No : CDN 339280
Chassis No : WAUZZZ8K7D232633
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 12-May-20
Place of Accident : Mount Elizabeth Link Traffic Light

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SFS 989 B

S/n	Nature of Jobs	Estimated Charges	Survivor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Re-organise crash management components. Reinstall all parts removed.	\$ 2,450.00	1250
3	To respray front bumper and rhs front fender.	\$ 2,000.00	1100
4	To carry out pre-wheel alignment and post-wheel alignment. To renew rhs front rim.	S/N \$ 520.00	x
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 5,522.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SFS 989 B

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Replaced</i>	\$ 2,581.00	✓
2	FRONT BUMPER FIXING PARTS <i>New</i>	\$ 244.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>New</i>	\$ 215.00	+
4	FRONT BUMPER GRILLE - LOWER CENTRE <i>New</i>	\$ 310.00	+
5	FRONT BUMPER CLOSING ELEMENT - UPPER CENTRE <i>New</i>	\$ 183.00	+
6	VENT GRILLE - RH <i>It</i>	\$ 545.00	✓
7	FRONT WHEEL SPOILER - RH ?	\$ 48.00	?
8	FRONT BUMPER GUIDE SECTION - RH ?	\$ 34.00	?
9	FRONT FENDER - RH <i>Dented</i>	\$ 932.00	✓
10	FRONT FENDER ATTACHMENT PARTS ?	\$ 54.00	?
11	FRONT FENDER BRACKET - RH FRONT <i>Dented</i>	\$ 50.00	✓
12	DEFORMATION ELEMENT BRACKET - RH REAR ?	\$ 46.00	?
13	FRONT FENDER BRACE - RH LOWER ?	\$ 112.00	?
14	STONE CHIP GUARD <i>re</i>	\$ 69.00	✓
15	ADHESIVE TAPE ?	\$ 52.00	?
16	WHEEL HOUSING LINER <i>Replaced</i>	\$ 226.00	✓
17	WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$ 42.00	?
18	HEADLIGHT MOUNTING - RH ?	\$ 112.00	?
19	HEADLAMP BRACKET- RH ?	\$ 100.00	?
20	HEADLIGHT - RH <i>cracked</i>	\$ 2,208.00	✓
21	LIFT CYLINDER- RH <i>New</i>	\$ 198.00	+
22	S-LINE INSCRIPTION <i>Re</i>	\$ 117.00	✓
23	FRONT RIM - RH <i>New</i>	TBC	+
24	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS		: \$ 8,778.00	
TOTAL LABOUR CHARGES		: \$ 5,522.00	
GRAND TOTAL		: \$ 14,300.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 22/05/20
Authorised Date :
Excess Cost :
Liability :
Remarks : NE Authensed, 04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant